



## NERI MOTORI Stock List

Part No : T80A2

Part No : 0,18 kw 1400 B14- made in China

Part No : 0,18 kw 1400 B14- made in China

Part No : 0,18 kw 1400 B14- made in China

Part No : 0,18 kw 1400 B14- made in China

Part No : 0,18 kw 1400 B14- made in China

Part No : 0,18 kw 1400 B14- made in China

Part No : 0,18 kw 1400 B14- made in China

Part No : 0,18 kw 1400 B14- made in China

Part No : 0,18 kw 1400 B14- made in China

Part No : 0,18 kw 1400 B14- made in China

Part No : 0,18 kw 1400 B14- made in China

Part No : 0,18 kw 1400 B14- made in Italy

Part No : 0,18 kw 1400 B14- made in Italy

Part No : 0,18 kw 1400 B14- made in Italy

Part No : 0,18 kw 1400 B14- made in Italy

Part No : 0,18 kw 1400 B14- made in Italy

Part No : 0,18 kw 1400 B14- made in Italy

Part No : 0.18/0.06KW 2 SPEED â€™Câ€™™ FLANGE MOUNTED MOTOR

Part No : 0.18/0.06KW 2 SPEED â€™Câ€™™ FLANGE MOUNTED MOTOR

Part No : 0.18/0.06KW 2 SPEED â€™Câ€™™ FLANGE MOUNTED MOTOR

Part No : 0.18/0.06KW 2 SPEED â€™Câ€™™ FLANGE MOUNTED MOTOR

Part No : 025HP4PB5SERFRE

Part No : 03012226

Part No : 03050161

Part No : 0505289200

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : 0802014007  
Part No : 08053872003  
Part No : 1 MC71C4  
Part No : 1 MC71C4  
Part No : 1 MC71C4  
Part No : 1 MC71C4  
Part No : 1 MC71C4  
Part No : 1 MC71C4  
Part No : 1 MC71C4  
Part No : 1 MC71C4  
Part No : 1 MC71C4  
Part No : 1 MC71C4

Part No : 100 A, 230/400, 50 hz, 3 Hp, 2,2 kw, 1410 rpm  
Part No : 100 A, 230/400, 50 hz, 3 Hp, 2,2 kw, 1410 rpm  
Part No : 100 A, 230/400, 50 hz, 3 Hp, 2,2 kw, 1410 rpm  
Part No : 100 A, 230/400, 50 hz, 3 Hp, 2,2 kw, 1410 rpm  
Part No : 100 A, 230/400, 50 hz, 3 Hp, 2,2 kw, 1410 rpm  
Part No : 100 A, 230/400, 50 hz, 3 Hp, 2,2 kw, 1410 rpm  
Part No : 100 A, 230/400, 50 hz, 3 Hp, 2,2 kw, 1410 rpm  
Part No : 100 A, 230/400, 50 hz, 3 Hp, 2,2 kw, 1410 rpm  
Part No : 100 A, 230/400, 50 hz, 3 Hp, 2,2 kw, 1410 rpm

Part No : 10008848002  
Part No : 10008848002  
Part No : 10008848002  
Part No : 10008848002  
Part No : 10008848002  
Part No : 10008848002

Part No : 100199010051- obsolete, replaced by DP132S-4/8-B3 and DP132M-4/8-B3  
Part No : 100199010051- obsolete, replaced by DP132S-4/8-B3 and DP132M-4/8-B3  
Part No : 100199010051- obsolete, replaced by DP132S-4/8-B3 and DP132M-4/8-B3  
Part No : 100199010051- obsolete, replaced by DP132S-4/8-B3 and DP132M-4/8-B3  
Part No : 100199010051- obsolete, replaced by DP132S-4/8-B3 and DP132M-4/8-B3  
Part No : 100199010051- obsolete, replaced by DP132S-4/8-B3 and DP132M-4/8-B3  
Part No : 100199010051- obsolete, replaced by DP132S-4/8-B3 and DP132M-4/8-B3  
Part No : 100199010051- obsolete, replaced by DP132S-4/8-B3 and DP132M-4/8-B3

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : 100199010051- obsolete, replaced by DP132S-4/8-B3 and DP132M-4/8-B3

Part No : 10051797009

Part No : 10051797009

Part No : 10051797009

Part No : 10051797009

Part No : 10051797009

Part No : 10051797009

Part No : 10051797009

Part No : 10051797009

Part No : 10051797009

Part No : 10051797009

Part No : 10051797009

Part No : 10052655008

Part No : 10052655008

Part No : 10052655008

Part No : 10052655008

Part No : 10052655008

Part No : 10052655008

Part No : 10054336015 replaced by DNB0M056B41-B14

Part No : 10054336015 replaced by DNB0M056B41-B14

Part No : 10054336015 replaced by DNB0M056B41-B14

Part No : 10054336015 replaced by DNB0M056B41-B14

Part No : 10054336015 replaced by DNB0M056B41-B14

Part No : 10054336015 replaced by DNB0M056B41-B14

Part No : 10054336015 replaced by DNB0M056B41-B14

Part No : 10054336015 replaced by DNB0M056B41-B14

Part No : 10054336015 replaced by DNB0M056B41-B14

Part No : 10054336015 replaced by DNB0M056B41-B14

Part No : 11050907001 T50B4

Part No : 11050907001 T50B4

Part No : 11050907001 T50B4

Part No : 11050907001 T50B4

Part No : 11050907001 T50B4

Part No : 11050907001 T50B4

Part No : 11050907001 T50B4

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : 11050907001 T50B4  
Part No : 11050907001 T50B4  
Part No : 11051079001  
Part No : 11051079001  
Part No : 11051079001  
Part No : 11051079001  
Part No : 11051079001  
Part No : 11051079001  
Part No : 11051079001  
Part No : 11051079001  
Part No : 12009997001008 OEM  
Part No : 12009997001008 OEM  
Part No : 12009997001008 OEM  
Part No : 12009997001008 OEM  
Part No : 12009997001008 OEM  
Part No : 12009997001008 OEM  
Part No : 12009997001008 OEM  
Part No : 12009997001008 OEM  
Part No : 12009997001008 OEM  
Part No : 13002211002  
Part No : 13002211002  
Part No : 13002211002  
Part No : 13002211002  
Part No : 13002211002  
Part No : 13002211002  
Part No : 1301064603  
Part No : 1301064603  
Part No : 1301064603  
Part No : 1301064603  
Part No : 1301064603  
Part No : 1301064603  
Part No : 1301064603  
Part No : 1301064603  
Part No : 1301064603  
Part No : 1301064603  
Part No : 13072104141

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : 13072104141  
Part No : 13072104141  
Part No : 13072104141  
Part No : 13072104141  
Part No : 13072104141  
Part No : 13072104141  
Part No : 13072104141  
Part No : 13072104141  
Part No : 14100000000000  
Part No : 14100000000000  
Part No : 14100000000000  
Part No : 14100000000000  
Part No : 14100000000000  
Part No : 14100000000000  
Part No : 14100000000000  
Part No : 14100000000000  
Part No : 14100000000000  
Part No : 15000000000000  
Part No : 15000000000000  
Part No : 15000000000000  
Part No : 15000000000000  
Part No : 15000000000000  
Part No : 15000000000000  
Part No : 15000000000000  
Part No : 15000000000000  
Part No : 15000000000000  
Part No : 15000000000000  
Part No : 15000000000000  
Part No : 15000000000000  
Part No : 1568N/2 N931  
Part No : 1568N/2 N931  
Part No : 1568N/2 N931  
Part No : 1568N/2 N931  
Part No : 1568N/2 N931  
Part No : 1568N/2 N931  
Part No : 1568N/2 N931  
Part No : 1568N/2 N931  
Part No : 1568N/2 N931  
Part No : 156A2

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : 156B4  
Part No : 16100000000000  
Part No : 16100000000000  
Part No : 16100000000000  
Part No : 16100000000000  
Part No : 16100000000000  
Part No : 16100000000000  
Part No : 16100000000000  
Part No : 16100000000000  
Part No : 16100000000000  
Part No : 16100000000000  
Part No : 16100000000000  
Part No : 16100000000000  
Part No : 16100000000000  
Part No : 17000000000000  
Part No : 17000000000000  
Part No : 17000000000000  
Part No : 17000000000000  
Part No : 17000000000000  
Part No : 17000000000000  
Part No : 17000000000000  
Part No : 17000000000000  
Part No : 17000000000000  
Part No : 17000000000000  
Part No : 18002069003005  
Part No : 19004924001001  
Part No : 2000008871  
Part No : 2000008871  
Part No : 2000008871  
Part No : 2000008871  
Part No : 2000008871  
Part No : 2000008871  
Part No : 2000008871  
Part No : 2000015339  
Part No : 2000015339  
Part No : 2000015339  
Part No : 2000015339

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : 2000015339  
Part No : 2000015339  
Part No : 2000015339  
Part No : 2000016138  
Part No : 2000016138  
Part No : 2000016138  
Part No : 2000016138  
Part No : 2000016138  
Part No : 2000016138  
Part No : 2000016138  
Part No : 2000016138  
Part No : 2000016138  
Part No : 2000016138  
Part No : 2000016138  
Part No : 2000016836  
Part No : 2000016836  
Part No : 2000016836  
Part No : 2000016836  
Part No : 2000016836  
Part No : 2000016836  
Part No : 2000016836  
Part No : 2000016836  
Part No : 2000016836  
Part No : 2000016868  
Part No : 2000016868  
Part No : 2000016868  
Part No : 2000016868  
Part No : 2000016868  
Part No : 2000016868  
Part No : 2000016868  
Part No : 20002921003  
Part No : 20020310000  
Part No : 20020310000  
Part No : 20020310000  
Part No : 20020310000  
Part No : 20020310000

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : 20020310000  
Part No : 20020310000  
Part No : 204774101  
Part No : 204774101  
Part No : 204774101  
Part No : 204774101  
Part No : 204774101  
Part No : 204774101  
Part No : 204774101  
Part No : 204774101  
Part No : 204774101  
Part No : 204774101  
Part No : 204774101  
Part No : 204774101  
Part No : 2204-0485  
Part No : 2204-0485  
Part No : 2204-0485  
Part No : 2204-0485  
Part No : 2204-0485  
Part No : 2204-0485  
Part No : 2204-0485  
Part No : 2204-0485  
Part No : 2206921001  
Part No : 2206921001  
Part No : 2206921001  
Part No : 2206921001  
Part No : 2206921001  
Part No : 2206921001  
Part No : 2206921001  
Part No : 2206921001  
Part No : 2206921001  
Part No : 2206921001  
Part No : 2206921001  
Part No : 230/400  
Part No : 230/400  
Part No : 230/400  
Part No : 230/400  
Part No : 230/400  
Part No : 230/400

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)



Part No : 230/400  
Part No : 230/400  
Part No : 230/400  
Part No : 230/400  
Part No : 240/415  
Part No : 240/415  
Part No : 240/415  
Part No : 240/415  
Part No : 240/415  
Part No : 240/415  
Part No : 240/415  
Part No : 240/415  
Part No : 271352  
Part No : 271352  
Part No : 271352  
Part No : 271352  
Part No : 271352  
Part No : 280/480  
Part No : 280/480  
Part No : 280/480  
Part No : 280/480  
Part No : 280/480  
Part No : 280/480  
Part No : 280/480  
Part No : 280/480  
Part No : 280/480  
Part No : 280/480  
Part No : 280/480  
Part No : 280/480  
Part No : 3 171A2  
Part No : 3 171A2  
Part No : 3 171A2  
Part No : 3 171A2  
Part No : 3 171A2  
Part No : 3 171A2  
Part No : 3 171A2  
Part No : 3 171A2  
Part No : 3 171A2  
Part No : 3 171A2  
Part No : 3 171A2  
Part No : 3 171A2

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : 3 171A2

Part No : 3 T132ML4

Part No : 3 T63B2 12050221002 POWER RATING : 0.3 KW SPEED : 50 TO 550 RPM IP55

Part No : 3 T63B2 12050221002 POWER RATING : 0.3 KW SPEED : 50 TO 550 RPM IP55

Part No : 3 T63B2 12050221002 POWER RATING : 0.3 KW SPEED : 50 TO 550 RPM IP55

Part No : 3 T63B2 12050221002 POWER RATING : 0.3 KW SPEED : 50 TO 550 RPM IP55

Part No : 3 T63B2 12050221002 POWER RATING : 0.3 KW SPEED : 50 TO 550 RPM IP55

Part No : 3 T63B2 12050221002 POWER RATING : 0.3 KW SPEED : 50 TO 550 RPM IP55

Part No : 3 T63B2 12050221002 POWER RATING : 0.3 KW SPEED : 50 TO 550 RPM IP55

Part No : 3 T63B2 12050221002 POWER RATING : 0.3 KW SPEED : 50 TO 550 RPM IP55

Part No : 3- IEC 34-1

Part No : 3- IEC 34-1

Part No : 3- IEC 34-1

Part No : 3- IEC 34-1

Part No : 3- IEC 34-1

Part No : 3- IEC 34-1

Part No : 3- IEC 34-1

Part No : 3- IEC 34-1

Part No : 3- IEC 34-1

Part No : 30 " A " 4 NO: 03040857

Part No : 30 " A " 4 NO: 03040857

Part No : 30 " A " 4 NO: 03040857

Part No : 30 " A " 4 NO: 03040857

Part No : 30 " A " 4 NO: 03040857

Part No : 30 " A " 4 NO: 03040857

Part No : 3100070713

Part No : 3100070713

Part No : 3100070713

Part No : 3100070713

Part No : 3100070713

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : 3100070713

Part No : 3100070713

Part No : 3100070713

Part No : 3100070713

Part No : 3320RPM 0.16KW AT56B2

Part No : 3PH MOT T56A4, NR 0601053700, S1, 230/400 V, 0,06 KW,1360 1/MIN

Part No : 3PH MOT T56A4, NR 0601053700, S1, 230/400 V, 0,06 KW,1360 1/MIN

Part No : 3PH MOT T56A4, NR 0601053700, S1, 230/400 V, 0,06 KW,1360 1/MIN

Part No : 3PH MOT T56A4, NR 0601053700, S1, 230/400 V, 0,06 KW,1360 1/MIN

Part No : 3PH MOT T56A4, NR 0601053700, S1, 230/400 V, 0,06 KW,1360 1/MIN

Part No : 3PH MOT T56A4, NR 0601053700, S1, 230/400 V, 0,06 KW,1360 1/MIN

Part No : 3~MOTOR 53 34

Part No : 3~MOTOR 53 34

Part No : 3~MOTOR 53 34

Part No : 3~MOTOR 53 34

Part No : 3~MOTOR 53 34

Part No : 3~MOTOR 53 34

Part No : 3~MOTOR 53 34

Part No : 3~MOTOR 53 34

Part No : 3~MOTOR 53 34

Part No : 3~Mot: DP63C2/8

Part No : 3~Mot: DP63C2/8

Part No : 3~Mot: DP63C2/8

Part No : 3~Mot: DP63C2/8

Part No : 3~Mot: DP63C2/8

Part No : 4 Poli 230/400/50 B14 0,12 kW

Part No : 40053513043 IC410 VF 44 A,  $\Delta^\circ = 60$  P71 B14 B3

Part No : 40053513043 IC410 VF 44 A,  $\Delta^\circ = 60$  P71 B14 B3

Part No : 40053513043 IC410 VF 44 A,  $\Delta^\circ = 60$  P71 B14 B3

Part No : 40053513043 IC410 VF 44 A,  $\Delta^\circ = 60$  P71 B14 B3

Part No : 40053513043 IC410 VF 44 A,  $\Delta^\circ = 60$  P71 B14 B3

Part No : 40053513043 IC410 VF 44 A,  $\Delta^\circ = 60$  P71 B14 B3

Part No : 40053513043 IC410 VF 44 A,  $\Delta^\circ = 60$  P71 B14 B3

Part No : 40053513043 IC410 VF 44 A,  $\Delta^\circ = 60$  P71 B14 B3

Part No : 40053513043 IC410 VF 44 A,  $\Delta^\circ = 60$  P71 B14 B3

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : 4P B5 0.25HP (M63 b4)  
Part No : 4P B5 0.25HP (M63 b4)  
Part No : 4P B5 0.25HP (M63 b4)  
Part No : 4P B5 0.25HP (M63 b4)  
Part No : 4P B5 0.25HP (M63 b4)  
Part No : 4P B5 0.25HP (M63 b4)  
Part No : 4P B5 0.25HP (M63 b4)  
Part No : 4P B5 0.25HP (M63 b4)  
Part No : 4P B5 0.25HP (M63 b4)  
Part No : 4P B5 0.25HP (M63 b4)  
Part No : 4PM80B  
Part No : 5030242  
Part No : 5030242  
Part No : 5030242  
Part No : 5030242  
Part No : 5030242  
Part No : 5030242  
Part No : 5030242  
Part No : 5030242  
Part No : 5063497  
Part No : 5063497  
Part No : 5063497  
Part No : 5063497  
Part No : 5063497  
Part No : 5063497  
Part No : 5063497  
Part No : 5063497  
Part No : 5063497  
Part No : 5063497  
Part No : 5063497  
Part No : 6066008  
Part No : 6066008  
Part No : 6066008  
Part No : 6066008  
Part No : 6066008  
Part No : 6066008  
Part No : 6066008

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : 6066008  
Part No : 6076068  
Part No : 6076068  
Part No : 6076068  
Part No : 6076068  
Part No : 6076068  
Part No : 6076068  
Part No : 6076068  
Part No : 6076068  
Part No : 6076068  
Part No : 6076068  
Part No : 63AN-4  
Part No : 63B4 0,18 KW 1400 R/MIN  
Part No : 63B4 0,18 KW 1400 R/MIN  
Part No : 63B4 0,18 KW 1400 R/MIN  
Part No : 63B4 0,18 KW 1400 R/MIN  
Part No : 63B4 0,18 KW 1400 R/MIN  
Part No : 63B4 0,18 KW 1400 R/MIN  
Part No : 63B4 0,18 KW 1400 R/MIN  
Part No : 63B4 0,18 KW 1400 R/MIN  
Part No : 70090250  
Part No : 7010390001  
Part No : 705 123 700  
Part No : 705 123 700  
Part No : 705 123 700  
Part No : 705 123 700  
Part No : 705 123 700  
Part No : 705 123 700  
Part No : 705 123 700  
Part No : 7050913002  
Part No : 7050913002  
Part No : 7050913002  
Part No : 7050913002  
Part No : 7050913002  
Part No : 7050913002  
Part No : 7050913002

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : 7050913002  
Part No : 7050913002  
Part No : 7050913002  
Part No : 7051255  
Part No : 7051255  
Part No : 7051255  
Part No : 7051255  
Part No : 7051255  
Part No : 7051255  
Part No : 7051255  
Part No : 7051255  
Part No : 7051255  
Part No : 70611260003  
Part No : 70611260003  
Part No : 70611260003  
Part No : 70611260003  
Part No : 70611260003  
Part No : 70611260003  
Part No : 70611260003  
Part No : 70611260003  
Part No : 70611260003  
Part No : 710-4  
Part No : 710-4  
Part No : 710-4  
Part No : 710-4  
Part No : 710-4  
Part No : 710-4  
Part No : 710-4  
Part No : 710-4  
Part No : 71B-4-0,37KW/1400/B14 IP55  
Part No : 71B-4-0,37KW/1400/B14 IP55  
Part No : 71B-4-0,37KW/1400/B14 IP55  
Part No : 71B-4-0,37KW/1400/B14 IP55  
Part No : 71B-4-0,37KW/1400/B14 IP55

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : 71B-4-0,37KW/1400/B14 IP55

Part No : 71B-4-0,37KW/1400/B14 IP55

Part No : 71B4

Part No : 71B4

Part No : 71B4

Part No : 71B4

Part No : 71B4

Part No : 71B4

Part No : 71B4

Part No : 71B4

Part No : 71B4

Part No : 763C6

Part No : 763C6

Part No : 763C6

Part No : 763C6

Part No : 763C6

Part No : 763C6

Part No : 763C6

Part No : 763C6

Part No : 763C6

Part No : 763C6

Part No : 80A4-S1 #06062384,0.55KW

Part No : 8A0002 100B-4 NR.10129933037 230/400 V 3 KW 1430 U/MIN 11,2/6,44 A

Part No : 8A0002 100B-4 NR.10129933037 230/400 V 3 KW 1430 U/MIN 11,2/6,44 A

Part No : 8A0002 100B-4 NR.10129933037 230/400 V 3 KW 1430 U/MIN 11,2/6,44 A

Part No : 8A0002 100B-4 NR.10129933037 230/400 V 3 KW 1430 U/MIN 11,2/6,44 A

Part No : 8A0002 100B-4 NR.10129933037 230/400 V 3 KW 1430 U/MIN 11,2/6,44 A

Part No : 8A0002 100B-4 NR.10129933037 230/400 V 3 KW 1430 U/MIN 11,2/6,44 A

Part No : 8A0002 100B-4 NR.10129933037 230/400 V 3 KW 1430 U/MIN 11,2/6,44 A

Part No : 90 WIDE FLANGE BY T90L4

Part No : 90 WIDE FLANGE BY T90L4

Part No : 90 WIDE FLANGE BY T90L4

Part No : 90 WIDE FLANGE BY T90L4

Part No : 90 WIDE FLANGE BY T90L4

Part No : 90 WIDE FLANGE BY T90L4

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : 90 WIDE FLANGE BY T90L4

Part No : 90 WIDE FLANGE BY T90L4

Part No : 9052449026

Part No : 9052449026

Part No : 9052449026

Part No : 9052449026

Part No : 9052449026

Part No : 9052449026

Part No : 9052449026

Part No : 9052449026

Part No : 9052449026

Part No : A17 1B4 111 230/400V 50HZ 0,5HP 0,37KW 1370D/D

Part No : A17 1B4 111 230/400V 50HZ 0,5HP 0,37KW 1370D/D

Part No : A17 1B4 111 230/400V 50HZ 0,5HP 0,37KW 1370D/D

Part No : A17 1B4 111 230/400V 50HZ 0,5HP 0,37KW 1370D/D

Part No : A17 1B4 111 230/400V 50HZ 0,5HP 0,37KW 1370D/D

Part No : A17 1B4 111 230/400V 50HZ 0,5HP 0,37KW 1370D/D

Part No : A17 1B4 111 230/400V 50HZ 0,5HP 0,37KW 1370D/D

Part No : A17 1B4 111 230/400V 50HZ 0,5HP 0,37KW 1370D/D

Part No : A21039050V1

Part No : A21039050V1

Part No : A21039050V1

Part No : A21039050V1

Part No : A21039050V1

Part No : A21039050V1

Part No : AD132S2/8

Part No : AD63C2/6

Part No : AD63C2/6

Part No : AD63C2/6

Part No : AD63C2/6

Part No : AD63C2/6

Part No : AD63C2/6

Part No : AD63C2/6

Part No : AD63C2/6

Part No : AD63C2/6

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net



Part No : AE6384  
Part No : AE6384  
Part No : AE6384  
Part No : AE6384  
Part No : AE6384  
Part No : AE6384  
Part No : AE6384  
Part No : AE6384  
Part No : AE6384  
Part No : AI80B5-XXX  
Part No : AI80B5-XXX  
Part No : AI80B5-XXX  
Part No : AI80B5-XXX  
Part No : AI80B5-XXX  
Part No : AI80B5-XXX  
Part No : AI80B5-XXX  
Part No : AI80B5-XXX  
Part No : AI80D4  
Part No : AI80D4  
Part No : AI80D4  
Part No : AI80D4  
Part No : AI80D4  
Part No : AT 090LB 4  
Part No : AT 090LB 4  
Part No : AT 090LB 4  
Part No : AT 090LB 4  
Part No : AT 090LB 4  
Part No : AT 090LB 4  
Part No : AT 090LB 4  
Part No : AT 090LB 4  
Part No : AT 090LB 4  
Part No : AT 090LB 4  
Part No : AT 100B4  
Part No : AT 100B4  
Part No : AT 100B4  
Part No : AT 100B4

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : AT 100B4  
Part No : AT 100B4  
Part No : AT 100B4-B5  
Part No : AT 100B4-B5  
Part No : AT 100B4-B5  
Part No : AT 100B4-B5  
Part No : AT 100B4-B5  
Part No : AT 100B4-B5  
Part No : AT 100B4-B5  
Part No : AT 100B4-B5  
Part No : AT 100BL 4 B14 230/400 50 BRAKE 54D/243OP  
Part No : AT 100BL 4 B14 230/400 50 BRAKE 54D/243OP  
Part No : AT 100BL 4 B14 230/400 50 BRAKE 54D/243OP  
Part No : AT 100BL 4 B14 230/400 50 BRAKE 54D/243OP  
Part No : AT 100BL 4 B14 230/400 50 BRAKE 54D/243OP  
Part No : AT 100BL 4 B14 230/400 50 BRAKE 54D/243OP  
Part No : AT 100BL 4 B14 230/400 50 BRAKE 54D/243OP  
Part No : AT 100BL 4 B14 230/400 50 BRAKE 54D/243OP  
Part No : AT 56B 2P  
Part No : AT 56B 2P  
Part No : AT 56B 2P  
Part No : AT 56B 2P  
Part No : AT 56B 2P  
Part No : AT 56B 2P  
Part No : AT 56B 2P  
Part No : AT 56B 2P  
Part No : AT 56B 2P  
Part No : AT 56B 2P  
Part No : AT 56B 2P  
Part No : AT 56B 2P  
Part No : AT 56B 2P  
Part No : AT 56B 2P  
Part No : AT 63 B 4 B14  
Part No : AT 63 B 4 B14  
Part No : AT 63 B 4 B14  
Part No : AT 63 B 4 B14  
Part No : AT 63 B 4 B14

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : AT 63 B 4 B14  
Part No : AT 63 B 4 B14  
Part No : AT 63 B 4 B14  
Part No : AT 63 B 4 B14  
Part No : AT 63 B2 IP65 BRAKE  
Part No : AT 63 B2 IP65 BRAKE  
Part No : AT 63 B2 IP65 BRAKE  
Part No : AT 63 B2 IP65 BRAKE  
Part No : AT 63 B2 IP65 BRAKE  
Part No : AT 63 B2 IP65 BRAKE  
Part No : AT 63 B2 IP65 BRAKE  
Part No : AT 63 B2 IP65 BRAKE  
Part No : AT 63 B2 IP65 BRAKE  
Part No : AT 63 B2 IP65 BRAKE  
Part No : AT 63 B2 IP65 BRAKE  
Part No : AT 63B 4B5  
Part No : AT 71 B4  
Part No : AT 71 B4  
Part No : AT 71 B4  
Part No : AT 71 B4  
Part No : AT 71 B4  
Part No : AT 71 B4  
Part No : AT 71 B4  
Part No : AT 71 B4  
Part No : AT 71 B4  
Part No : AT 80A4-B14  
Part No : AT 80A4-B14  
Part No : AT 80A4-B14  
Part No : AT 80A4-B14  
Part No : AT 80A4-B14  
Part No : AT 80A4-B14  
Part No : AT 80A4-B14  
Part No : AT 80B 4 KW 0.75 4P B14 230/400 50  
Part No : AT 80B 4 KW 0.75 4P B14 230/400 50  
Part No : AT 80B 4 KW 0.75 4P B14 230/400 50  
Part No : AT 80B 4 KW 0.75 4P B14 230/400 50

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : AT 80B 4 KW 0.75 4P B14 230/400 50

Part No : AT 80B 4 KW 0.75 4P B14 230/400 50

Part No : AT 90L6

Part No : AT 90L6

Part No : AT 90L6

Part No : AT 90L6

Part No : AT 90L6

Part No : AT 90L6

Part No : AT 90L6

Part No : AT 90L6

Part No : AT F1 C4-B5

Part No : AT F1 C4-B5

Part No : AT F1 C4-B5

Part No : AT F1 C4-B5

Part No : AT F1 C4-B5

Part No : AT F1 C4-B5

Part No : AT F1 C4-B5

Part No : AT100A

Part No : AT100A

Part No : AT100A

Part No : AT100A

Part No : AT100A

Part No : AT100A

Part No : AT100A

Part No : AT100A

Part No : AT100A

Part No : AT100B

Part No : AT112A4

Part No : AT112B6

Part No : AT112B6

Part No : AT112B6

Part No : AT112B6

Part No : AT112B6

Part No : AT112B6

Part No : AT112B6

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : AT112B6  
Part No : AT112B6  
Part No : AT160M4  
Part No : AT160M4  
Part No : AT160M4  
Part No : AT160M4  
Part No : AT160M4  
Part No : AT160M4  
Part No : AT160M4  
Part No : AT160M4  
Part No : AT56C6-SONDER  
Part No : AT56C6-SONDER  
Part No : AT56C6-SONDER  
Part No : AT56C6-SONDER  
Part No : AT56C6-SONDER  
Part No : AT56C6-SONDER  
Part No : AT56C6-SONDER  
Part No : AT56C6-SONDER  
Part No : AT63 BN76  
Part No : AT63 BN76  
Part No : AT63 BN76  
Part No : AT63 BN76  
Part No : AT63 BN76  
Part No : AT63 BN76  
Part No : AT63 BN76  
Part No : AT63 BN76  
Part No : AT63B 025 2P B14 V260/440/60  
Part No : AT63B 025 2P B14 V260/440/60  
Part No : AT63B 025 2P B14 V260/440/60  
Part No : AT63B 025 2P B14 V260/440/60  
Part No : AT63B 025 2P B14 V260/440/60  
Part No : AT63B 025 2P B14 V260/440/60  
Part No : AT63B 025 2P B14 V260/440/60  
Part No : AT63B 025 2P B14 V260/440/60  
Part No : AT63B4

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : AT63BT  
Part No : AT63R6  
Part No : AT63R6  
Part No : AT63R6  
Part No : AT63R6  
Part No : AT63R6  
Part No : AT63R6  
Part No : AT63R6  
Part No : AT63R6  
Part No : AT71B  
Part No : AT71B  
Part No : AT71B  
Part No : AT71B  
Part No : AT71B  
Part No : AT71B  
Part No : AT71B  
Part No : AT71B  
Part No : AT71B  
Part No : AT71C6  
Part No : AT80B  
Part No : AT80B  
Part No : AT80B  
Part No : AT80B  
Part No : AT80B  
Part No : AT80B  
Part No : AT80B  
Part No : AT80B  
Part No : AT80B  
Part No : AT80B  
Part No : AT80B 2  
Part No : AT80B 2  
Part No : AT80B 2  
Part No : AT80B 2  
Part No : AT80B 2  
Part No : AT80B 2  
Part No : AT80B 2

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : AT80B 2  
Part No : AT80B 2  
Part No : AT80B2 1.3KW , 3420RPM  
Part No : AT80B2 1.3KW , 3420RPM  
Part No : AT80B2 1.3KW , 3420RPM  
Part No : AT80B2 1.3KW , 3420RPM  
Part No : AT80B2 1.3KW , 3420RPM  
Part No : AT80B2 1.3KW , 3420RPM  
Part No : AT80B2 13050980003053  
Part No : AT80B2 13050980003053  
Part No : AT80B2 13050980003053  
Part No : AT80B2 13050980003053  
Part No : AT80B2 13050980003053  
Part No : AT80B2 13050980003053  
Part No : AT80B2 13050980003053  
Part No : AT80B2 13050980003053  
Part No : AT80B4  
Part No : AT80B4  
Part No : AT80B4  
Part No : AT80B4  
Part No : AT80B4  
Part No : AT80B4  
Part No : AT80B4  
Part No : AT80B4  
Part No : AT80B4  
Part No : AT80B4 B5  
Part No : AT80B4 B5  
Part No : AT80B4 B5  
Part No : AT80B4 B5  
Part No : AT80B4 B5  
Part No : AT80B4 B5  
Part No : AT80B4 B5  
Part No : AT80B4 B5  
Part No : AT80B4 B5  
Part No : AT80B4 B5  
Part No : AT80B4 B5  
Part No : AT80B4 B5

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : AT80B4 B5  
Part No : AT80B6  
Part No : AT80C2  
Part No : AT80C6  
Part No : AT90L4  
Part No : AT90L4 + GEARBOX  
Part No : AT90L6  
Part No : B1 TP111  
Part No : B1 TP111  
Part No : B1 TP111  
Part No : B1 TP111  
Part No : B1 TP111  
Part No : B1 TP111  
Part No : B1 TP111  
Part No : B1 TP111  
Part No : B1 TP111  
Part No : B1 TP111  
Part No : B1 TP111  
Part No : BFK 180VDC  
Part No : BFK 180VDC  
Part No : BFK 180VDC  
Part No : BFK 180VDC  
Part No : BFK 180VDC  
Part No : BFK 180VDC  
Part No : BFK 180VDC  
Part No : BFK 180VDC  
Part No : BFK 180VDC  
Part No : BFK-06-Rotor  
Part No : BFK-06-Rotor  
Part No : BFK-06-Rotor  
Part No : BFK-06-Rotor  
Part No : BFK-06-Rotor  
Part No : BFK-06-Rotor  
Part No : BFK-06-Rotor  
Part No : BFK-06-Rotor  
Part No : BFK-06-Rotor  
Part No : BFK-06-Rotor  
Part No : BFK458-06E-205V  
Part No : BFK458-06E-205V

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net



Part No : BFK458-06E-205V  
Part No : BFK458-06E-205V  
Part No : BFK458-06E-205V  
Part No : BFK458-06E-205V  
Part No : BFK458-06E-205V  
Part No : BFK458-06E-205V  
Part No : Brake assy for 11005785009  
Part No : Brake assy for 11005785009  
Part No : Brake assy for 11005785009  
Part No : Brake assy for 11005785009  
Part No : Brake assy for 11005785009  
Part No : Brake assy for 11005785009  
Part No : Brake assy for 11005785009  
Part No : Brake for AD112B2/4  
Part No : Brake for AD112B2/4  
Part No : Brake for AD112B2/4  
Part No : Brake for AD112B2/4  
Part No : Brake for AD112B2/4  
Part No : Brake for AD112B2/4  
Part No : Brake for AD112B2/4  
Part No : Brake for AD112B2/4  
Part No : Brake for AD112B2/4  
Part No : Brake for AD112B2/4  
Part No : Brake for AT100A4  
Part No : Brake for AT100A4  
Part No : Brake for AT100A4  
Part No : Brake for AT100A4  
Part No : Brake for AT100A4  
Part No : Brake for AT100A4  
Part No : Brake for AT100A4  
Part No : Brake for AT100A4  
Part No : Brake for AT100A4  
Part No : Brake for AT100A4  
Part No : Brake for AT100A4  
Part No : Brake for AT100A4  
Part No : Brake for AT100A4  
Part No : Brake for AT100A4  
Part No : Brake for motor AT63B6

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : Brake for motor AT63B6  
Part No : Brake for motor AT63B6  
Part No : Brake for motor AT63B6  
Part No : Brake for motor AT63B6  
Part No : Brake for motor AT63B6  
Part No : Cooling fan for T80BN/4  
Part No : Cooling fan for T80BN/4  
Part No : Cooling fan for T80BN/4  
Part No : Cooling fan for T80BN/4  
Part No : Cooling fan for T80BN/4  
Part No : Cooling fan for T80BN/4  
Part No : Cooling fan for T80BN/4  
Part No : Cooling fan for T80BN/4  
Part No : DFRA-1100/1300  
Part No : DNB00100B41-B14  
Part No : DNB00100B41-B14  
Part No : DNB00100B41-B14  
Part No : DNB00100B41-B14  
Part No : DNB00100B41-B14  
Part No : DNB00100B41-B14  
Part No : DNB00100B41-B14  
Part No : DNB00100B41-B14  
Part No : DNB00100B41-B14  
Part No : DNB00100B41-B14  
Part No : DNB00100B41-B14  
Part No : DNB00100B41-B14  
Part No : DNB00100B41-B14  
Part No : DNB01063B41-B14  
Part No : DNB01063B41-B14  
Part No : DNB01063B41-B14  
Part No : DNB01063B41-B14  
Part No : DNB01063B41-B14  
Part No : DNB01063B41-B14  
Part No : DNB01063B41-B14  
Part No : DNB01063B41-B14  
Part No : DNB01063B41-B14  
Part No : DNB01063B41-B14  
Part No : DNB01063B41-B14-2  
Part No : DNB01063C61-B14 / IN63C6

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States  
Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web:  
<http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : DNB0I063C61-B14 / IN63C6  
Part No : DNB0I063C61-B14 / IN63C6  
Part No : DNB0I063C61-B14 / IN63C6  
Part No : DNB0I063C61-B14 / IN63C6  
Part No : DNB0I063C61-B14 / IN63C6  
Part No : DNB0I063C61-B14 / IN63C6  
Part No : DNB0I063C61-B5  
Part No : DNB0I063C61-B5  
Part No : DNB0I063C61-B5  
Part No : DNB0I063C61-B5  
Part No : DNB0I063C61-B5  
Part No : DNB0I063C61-B5  
Part No : DNB0I063C61-B5  
Part No : DNB0I063C61-B5  
Part No : DNB0I063C61-B5  
Part No : DNB0I071A41-B14  
Part No : DNB0I071A41-B14  
Part No : DNB0I071A41-B14  
Part No : DNB0I071A41-B14  
Part No : DNB0I071A41-B14  
Part No : DNB0I071A41-B14  
Part No : DNB0I071A41-B14  
Part No : DNB0I071A41-B14  
Part No : DNB0I071A41-B14  
Part No : DNB0I071A41-B14  
Part No : DNB0I071A41-B14  
Part No : DNB0I071A41-B14  
Part No : DNB0I071A41-B14  
Part No : DNB0M056B41-B14  
Part No : DNB0M056B41-B14  
Part No : DNB0M056B41-B14  
Part No : DNB0M056B41-B14  
Part No : DNB0M056B41-B14  
Part No : DNB0M056B41-B14  
Part No : DNB0M056B41-B14  
Part No : DNB0M063C41-B3  
Part No : DNB0R063B21-B14 / MR63B2  
Part No : DNB0R063B21-B14 / MR63B2  
Part No : DNB0R063B21-B14 / MR63B2

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : DNB0R063B21-B14 / MR63B2  
Part No : DNB0R063B21-B14 / MR63B2  
Part No : DNB0R063B21-B14 / MR63B2  
Part No : DNB0R063B21-B14 / MR63B2  
Part No : DNB0R071B41-B5 / MR71B4  
Part No : DNB0R071B41-B5 / MR71B4  
Part No : DNB0R071B41-B5 / MR71B4  
Part No : DNB0R071B41-B5 / MR71B4  
Part No : DNB0R071B41-B5 / MR71B4  
Part No : DNB0R071B41-B5 / MR71B4  
Part No : DNB0R071B41-B5 / MR71B4  
Part No : DNB0R071B41-B5 / MR71B4  
Part No : DNB0R080A41-B14  
Part No : DNB0T056B41-B14  
Part No : DNB0T063B41-B5  
Part No : DNB0T063D41-B14  
Part No : DNB0T080A41-B14  
Part No : DNB0T080B41-B5  
Part No : DNB0T090L41-B5  
Part No : DNE0I080FL1-CS  
Part No : DNE0I090FL1-CS  
Part No : DO9000A1800  
Part No : DO9000A1800  
Part No : DO9000A1800  
Part No : DO9000A1800  
Part No : DO9000A1800  
Part No : DO9000A1800  
Part No : DO9000A1800  
Part No : DO9000A1800  
Part No : DO9000A1800  
Part No : DP 112A 2/8 3,0/0,75 kWt 6,8?3,3A 2900/710 turn/min 33kg 380V  
Part No : DP 112A 2/8 3,0/0,75 kWt 6,8?3,3A 2900/710 turn/min 33kg 380V  
Part No : DP 112A 2/8 3,0/0,75 kWt 6,8?3,3A 2900/710 turn/min 33kg 380V  
Part No : DP 112A 2/8 3,0/0,75 kWt 6,8?3,3A 2900/710 turn/min 33kg 380V  
Part No : DP 112A 2/8 3,0/0,75 kWt 6,8?3,3A 2900/710 turn/min 33kg 380V

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : DP 112A 2/8 3,0/0,75 kWt 6,8?3,3A 2900/710 turn/min 33kg 380V  
Part No : DP 112A 2/8 3,0/0,75 kWt 6,8?3,3A 2900/710 turn/min 33kg 380V  
Part No : DP 112A 2/8 3,0/0,75 kWt 6,8?3,3A 2900/710 turn/min 33kg 380V  
Part No : DP 112A 2/8 3,0/0,75 kWt 6,8?3,3A 2900/710 turn/min 33kg 380V  
Part No : DP 112A 2/8 3,0/0,75 kWt 6,8?3,3A 2900/710 turn/min 33kg 380V  
Part No : DP 132M  
Part No : DP 132M  
Part No : DP 132M  
Part No : DP 132M  
Part No : DP 132M  
Part No : DP 132M  
Part No : DP 132M  
Part No : DP 132M  
Part No : DP 132M  
Part No : DP 132M  
Part No : DP 132M  
Part No : DP 63C 2/8  
Part No : DP 63C 2/8  
Part No : DP 63C 2/8  
Part No : DP 63C 2/8  
Part No : DP 63C 2/8  
Part No : DP 63C 2/8  
Part No : DP 63C 2/8  
Part No : DP 71B 2/4 P B14 V.400/500  
Part No : DP 71B 2/4 P B14 V.400/500  
Part No : DP 71B 2/4 P B14 V.400/500  
Part No : DP 71B 2/4 P B14 V.400/500  
Part No : DP 71B 2/4 P B14 V.400/500  
Part No : DP 71B 2/4 P B14 V.400/500  
Part No : DP 71B 2/4 P B14 V.400/500  
Part No : DP 71B 2/4 P B14 V.400/500  
Part No : DP 71B 2/4 P B14 V.400/500  
Part No : DP 71B 2/4 P B14 V.400/500  
Part No : DP 80B 4/8 P  
Part No : DP 80B 4/8 P  
Part No : DP 80B 4/8 P  
Part No : DP 80B 4/8 P  
Part No : DP 80B 4/8 P

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : DP 80B 4/8 P  
Part No : DP 80B 4/8 P  
Part No : DP100BL  
Part No : DP100BL  
Part No : DP100BL  
Part No : DP100BL  
Part No : DP100BL  
Part No : DP100BL  
Part No : DP100BL  
Part No : DP100BL  
Part No : DP100BL  
Part No : DP112B2/4  
Part No : DP132M-4/8-B3  
Part No : DP132M-4/8-B3  
Part No : DP132M-4/8-B3  
Part No : DP132M-4/8-B3  
Part No : DP132M-4/8-B3  
Part No : DP132M-4/8-B3  
Part No : DP132M-4/8-B3  
Part No : DP132M-4/8-B3  
Part No : DP132M-4/8-B3  
Part No : DP132M-4/8-B3  
Part No : DP132M-4/8-B3  
Part No : DP132S-4/8-B3  
Part No : DP132S-4/8-B3  
Part No : DP132S-4/8-B3  
Part No : DP132S-4/8-B3  
Part No : DP132S-4/8-B3  
Part No : DP132S-4/8-B3  
Part No : DP132S-4/8-B3  
Part No : DP132S-4/8-B3  
Part No : DP63C  
Part No : DP63C  
Part No : DP63C  
Part No : DP63C  
Part No : DP63C

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : DP63C  
Part No : DP71C 4/8 P  
Part No : DP71C 4/8 P  
Part No : DP71C 4/8 P  
Part No : DP71C 4/8 P  
Part No : DP71C 4/8 P  
Part No : DP71C 4/8 P  
Part No : DP71C 4/8 P  
Part No : DP71C 4/8 P  
Part No : DP71C 4/8 P  
Part No : DP90LB27  
Part No : DP90LB27  
Part No : DP90LB27  
Part No : DP90LB27  
Part No : DP90LB27  
Part No : EB0011BA2AM  
Part No : EB0011BA2AM  
Part No : EB0011BA2AM  
Part No : EB0011BA2AM  
Part No : EB0011BA2AM  
Part No : EB0011BA2AM  
Part No : EF0110B21AM  
Part No : EF0110B21AM  
Part No : EF0110B21AM  
Part No : EF0110B21AM  
Part No : EF0110B21AM  
Part No : EF0110B21AM  
Part No : EF0110B21AM  
Part No : EF0110B21AM  
Part No : EF0110B21AM  
Part No : EF0110B21AM  
Part No : EF0110B21AM  
Part No : EREFE000\_NERI  
Part No : EREFE000\_NERI  
Part No : EREFE000\_NERI

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : EREFE000\_NERI  
Part No : EREFE000\_NERI  
Part No : EREFE000\_NERI  
Part No : EREFE000\_NERI  
Part No : EREFE000\_NERI  
Part No : EREFE000\_NERI  
Part No : FDE-B2-BFK458-06  
Part No : FDE-B2-BFK458-06  
Part No : FDE-B2-BFK458-06  
Part No : FDE-B2-BFK458-06  
Part No : FDE-B2-BFK458-06  
Part No : FDE-B2-BFK458-06  
Part No : FDE-B2-BFK458-06  
Part No : FDE-B2-BFK458-06  
Part No : FDE-B2-BFK458-06  
Part No : FDE-B2-BFK458-06  
Part No : FDE-B2-BFK458-06  
Part No : FDE-N2-12-BFK458-06  
Part No : FDE-N2-12-BFK458-06  
Part No : FDE-N2-12-BFK458-06  
Part No : FDE-N2-12-BFK458-06  
Part No : FDE-N2-12-BFK458-06  
Part No : FDE-N2-12-BFK458-06  
Part No : FDE-N2-12-BFK458-06  
Part No : FM730 T71C4 B5  
Part No : FM730 T71C4 B5  
Part No : FM730 T71C4 B5  
Part No : FM730 T71C4 B5  
Part No : FM730 T71C4 B5  
Part No : FM730 T71C4 B5  
Part No : FM730 T71C4 B5  
Part No : FM730 T71C4 B5  
Part No : FM730 T71C4 B5  
Part No : Fan for 03019 70E0  
Part No : Fan for 03019 70E0  
Part No : Fan for 03019 70E0

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net



Part No : Fan for 03019 70E0  
Part No : Fan for 03019 70E0  
Part No : Fan for 03019 70E0  
Part No : Fan for 03019 70E0  
Part No : Fan for 03019 70E0  
Part No : Fan for 03019 70E0  
Part No : Fan for 03019 70E0  
Part No : Fan for 03019 70E0  
Part No : Gear Box Connector for Type MR90S-4  
Part No : Gear Box Connector for Type MR90S-4  
Part No : Gear Box Connector for Type MR90S-4  
Part No : Gear Box Connector for Type MR90S-4  
Part No : Gear Box Connector for Type MR90S-4  
Part No : Gear Box Connector for Type MR90S-4  
Part No : Gear Box Connector for Type MR90S-4  
Part No : Gear Box Connector for Type MR90S-4  
Part No : Gear Box Connector for Type MR90S-4  
Part No : HE2 80D KW 0.75 4P B3 MU+BISPORG  
Part No : HE2 80D KW 0.75 4P B3 MU+BISPORG  
Part No : HE2 80D KW 0.75 4P B3 MU+BISPORG  
Part No : HE2 80D KW 0.75 4P B3 MU+BISPORG  
Part No : HE2 80D KW 0.75 4P B3 MU+BISPORG  
Part No : HE2 80D KW 0.75 4P B3 MU+BISPORG  
Part No : HE2 80D KW 0.75 4P B3 MU+BISPORG  
Part No : HE2 80D KW 0.75 4P B3 MU+BISPORG  
Part No : HE2-71B4  
Part No : HE3 80D 075 4P B5 V230/400/50+PAM71  
Part No : HE3 80D 075 4P B5 V230/400/50+PAM71  
Part No : HE3 80D 075 4P B5 V230/400/50+PAM71  
Part No : HE3 80D 075 4P B5 V230/400/50+PAM71  
Part No : HE3 80D 075 4P B5 V230/400/50+PAM71  
Part No : HE3 80D 075 4P B5 V230/400/50+PAM71  
Part No : HE3 80D 075 4P B5 V230/400/50+PAM71  
Part No : HE3-132M4  
Part No : IC41 10053513043

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : IC41 10053513043  
Part No : IC41 10053513043  
Part No : IC41 10053513043  
Part No : IC41 10053513043  
Part No : IC41 10053513043  
Part No : IC411 14050564002028 IP 55  
Part No : IE1 MR100B KW 3 4P B14 230/400  
Part No : IE1 MR100B KW 3 4P B14 230/400  
Part No : IE1 MR100B KW 3 4P B14 230/400  
Part No : IE1 MR100B KW 3 4P B14 230/400  
Part No : IE1 MR100B KW 3 4P B14 230/400  
Part No : IE1 MR100B KW 3 4P B14 230/400  
Part No : IE1 MR100B KW 3 4P B14 230/400  
Part No : IE1 MR100B KW 3 4P B14 230/400  
Part No : IE1 MR100B KW 3 4P B14 230/400  
Part No : IEC 34-1 T90L4  
Part No : IEC 34-1 T90L4  
Part No : IEC 34-1 T90L4  
Part No : IEC 34-1 T90L4  
Part No : IEC 34-1 T90L4  
Part No : IEC 34-1 T90L4  
Part No : IEC 34-1 T90L4  
Part No : IEC 34-1 T90L4  
Part No : IEC 34-1 T90L4  
Part No : IEC CFL IP55 B5 (200/19)  
Part No : IEC CFL IP55 B5 (200/19)  
Part No : IEC CFL IP55 B5 (200/19)  
Part No : IEC CFL IP55 B5 (200/19)  
Part No : IEC CFL IP55 B5 (200/19)  
Part No : IEC CFL IP55 B5 (200/19)  
Part No : IEC CFL IP55 B5 (200/19)  
Part No : IEC CFL IP55 B5 (200/19)  
Part No : IEC CFL IP55 B5 (200/19)  
Part No : IEC CFL IP55 B5(140/11)  
Part No : IEC CFL IP55 B5(140/11)  
Part No : IEC CFL IP55 B5(140/11)

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : IEC CFL IP55 B5(140/11)  
Part No : IEC CFL IP55 B5(140/11)  
Part No : IEC CFL IP55 B5(140/11)  
Part No : IEC CFL IP55 B5(140/11)  
Part No : IEC CFL IP55 B5(140/11)  
Part No : IEC CFL IP55 B5(140/11)  
Part No : IEC CFL IP55 B5(140/11)  
Part No : IEC CLF IP55 B5 (200/24)  
Part No : IEC CLF IP55 B5 (200/24)  
Part No : IEC CLF IP55 B5 (200/24)  
Part No : IEC CLF IP55 B5 (200/24)  
Part No : IEC CLF IP55 B5 (200/24)  
Part No : IN 63D 4  
Part No : IN 63D 4  
Part No : IN 63D 4  
Part No : IN 63D 4  
Part No : IN 63D 4  
Part No : IN 63D 4  
Part No : IN 63D 4  
Part No : IN 63D 4  
Part No : IN 80B 4  
Part No : IN 80B 4  
Part No : IN 80B 4  
Part No : IN 80B 4  
Part No : IN 80B 4  
Part No : IN 80B 4  
Part No : IN 80B 4  
Part No : IN 80B 4  
Part No : IN 80B 4  
Part No : IN 80B 4  
Part No : IN112A6  
Part No : IN63B4 08008900002  
Part No : IN63B4 08008900002  
Part No : IN63B4 08008900002  
Part No : IN63B4 08008900002  
Part No : IN63B4 08008900002  
Part No : IN63B4 08008900002

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : IN63B4 08008900002

Part No : IN63D4

Part No : IN71C6

Part No : IN80B4

Part No : IN80B4

Part No : IN80B4

Part No : IN80B4

Part No : IN80B4

Part No : IN80B4

Part No : IN80C2

Part No : IN80D4

Part No : IT90L4

Part No : IT90L4

Part No : IT90L4

Part No : IT90L4

Part No : IT90L4

Part No : IT90L4

Part No : IT90L4

Part No : IT90L4

Part No : IT90L4

Part No : IT90L4

Part No : KS90SW04

Part No : KS90SW04

Part No : KS90SW04

Part No : KS90SW04

Part No : KS90SW04

Part No : KS90SW04

Part No : KS90SW04

Part No : KS90SW04

Part No : KS90SW04

Part No : KS90SW04

Part No : Lagerschilde fÃ¼r M80D4

Part No : Lagerschilde fÃ¼r M80D4

Part No : Lagerschilde fÃ¼r M80D4

Part No : Lagerschilde fÃ¼r M80D4

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : Lagerschilde fÃ¼r M80D4  
Part No : Lagerschilde fÃ¼r M80D4  
Part No : Lagerschilde fÃ¼r M80D4  
Part No : Lagerschilde fÃ¼r M80D4  
Part No : Lagerschilde fÃ¼r M80D4  
Part No : Lagerschilde fÃ¼r M80D4  
Part No : M036801  
Part No : M056BAT55F4  
Part No : M056BAT55F4  
Part No : M056BAT55F4  
Part No : M056BAT55F4  
Part No : M056BAT55F4  
Part No : M056BAT55F4  
Part No : M056BAT55F4  
Part No : M056BAT55F4  
Part No : M056BAT55F4  
Part No : M056BAT55F4  
Part No : M071C 4P  
Part No : M071C 4P  
Part No : M071C 4P  
Part No : M071C 4P  
Part No : M071C 4P  
Part No : M071C 4P  
Part No : M071C 4P  
Part No : M071C 4P  
Part No : M071C 4P  
Part No : M071C 4P  
Part No : M071C 4P  
Part No : M071C 4P  
Part No : M071C 4P  
Part No : M071C 4P  
Part No : M071C 4P  
Part No : M071C 4P  
Part No : M071C 4P  
Part No : M3 156B4  
Part No : M3 T56A2  
Part No : M3 T56A2  
Part No : M3 T56A2  
Part No : M3 T56A2  
Part No : M3 T56A2  
Part No : M3 T56A2  
Part No : M3 T56A2

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : M3 T56A2  
Part No : M3 T56A2  
Part No : M3 T56A2  
Part No : M3 T56A2  
Part No : M3 T63B2  
Part No : M56B 009 4P B14 V230/50  
Part No : M56B 009 4P B14 V230/50  
Part No : M56B 009 4P B14 V230/50  
Part No : M56B 009 4P B14 V230/50  
Part No : M56B 009 4P B14 V230/50  
Part No : M56B 009 4P B14 V230/50  
Part No : M56B 009 4P B14 V230/50  
Part No : M56B 009 4P B14 V230/50  
Part No : M63C4  
Part No : M63C4-B3  
Part No : M71B4  
Part No : M71C4  
Part No : M8084  
Part No : M8084  
Part No : M8084  
Part No : M8084  
Part No : M8084  
Part No : M8084  
Part No : M8084  
Part No : M8084  
Part No : M8084  
Part No : M80B 4 B3 220/60 IP55 CLF  
Part No : M80B 4 B5 230/440/1680RPM/SER  
Part No : M80B4  
Part No : M80C2 05051427007  
Part No : M80C2 05051427007  
Part No : M80C2 05051427007  
Part No : M80C2 05051427007  
Part No : M80C2 05051427007  
Part No : M80C2 05051427007  
Part No : M80C2 05051427007  
Part No : M80C2 05051427007  
Part No : M80C2 05051427007

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : M80C2 05051427007  
Part No : M80C2 05051427007  
Part No : M90S4  
Part No : M90SN/2  
Part No : MAF080 A4-0,55KW/1400RPM/B5/230-400V SC  
Part No : MAF080 A4-0,55KW/1400RPM/B5/230-400V SC  
Part No : MAF080 A4-0,55KW/1400RPM/B5/230-400V SC  
Part No : MAF080 A4-0,55KW/1400RPM/B5/230-400V SC  
Part No : MAF080 A4-0,55KW/1400RPM/B5/230-400V SC  
Part No : MAF080 A4-0,55KW/1400RPM/B5/230-400V SC  
Part No : MAF080 A4-0,55KW/1400RPM/B5/230-400V SC  
Part No : MAF080 A4-0,55KW/1400RPM/B5/230-400V SC  
Part No : MAF080 A4-0,55KW/1400RPM/B5/230-400V SC  
Part No : MAF090  
Part No : MAF090  
Part No : MAF090  
Part No : MAF090  
Part No : MAF090  
Part No : MAF090  
Part No : MAF090  
Part No : MAF090  
Part No : MAF090  
Part No : MAF090  
Part No : MC 71C 4  
Part No : MC 71C 4  
Part No : MC 71C 4  
Part No : MC 71C 4  
Part No : MC 71C 4  
Part No : MC 71C 4  
Part No : MC 71C 4  
Part No : MC 71C 4  
Part No : ME 63D 4 B14  
Part No : ME 63D 4 B14  
Part No : ME 63D 4 B14  
Part No : ME 63D 4 B14  
Part No : ME 63D 4 B14  
Part No : ME 63D 4 B14  
Part No : ME 63D 4 B14

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : ME 63D 4 B14  
Part No : ME 63D 4 B14  
Part No : MG200156059  
Part No : MG200156059  
Part No : MG200156059  
Part No : MG200156059  
Part No : MG200156059  
Part No : MG200156059  
Part No : MG200156059  
Part No : MG200156059  
Part No : MP90A0089 90L-4 1,5 kW 1410rpm  
Part No : MP90A0089 90L-4 1,5 kW 1410rpm  
Part No : MP90A0089 90L-4 1,5 kW 1410rpm  
Part No : MP90A0089 90L-4 1,5 kW 1410rpm  
Part No : MP90A0089 90L-4 1,5 kW 1410rpm  
Part No : MP90A0089 90L-4 1,5 kW 1410rpm  
Part No : MP90A0089 90L-4 1,5 kW 1410rpm  
Part No : MP90A0089 90L-4 1,5 kW 1410rpm  
Part No : MP90A0089 90L-4 1,5 kW 1410rpm  
Part No : MR 071B 4 B14  
Part No : MR 071B 4 B14  
Part No : MR 071B 4 B14  
Part No : MR 071B 4 B14  
Part No : MR 071B 4 B14  
Part No : MR 071B 4 B14  
Part No : MR 071B 4 B14  
Part No : MR 071B 4 B14  
Part No : MR 071B 4 B14  
Part No : MR 100B  
Part No : MR 100B  
Part No : MR 100B  
Part No : MR 100B  
Part No : MR 100B  
Part No : MR 100B  
Part No : MR 100B  
Part No : MR 100B

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)



Part No : MR 132S  
Part No : MR 132S  
Part No : MR 132S  
Part No : MR 132S  
Part No : MR 132S  
Part No : MR 132S  
Part No : MR 132S  
Part No : MR 132S  
Part No : MR 132S  
Part No : MR 80B 6 230/400 50  
Part No : MR 80B 6 230/400 50  
Part No : MR 80B 6 230/400 50  
Part No : MR 80B 6 230/400 50  
Part No : MR 80B 6 230/400 50  
Part No : MR 80B 6 230/400 50  
Part No : MR 80B 6 230/400 50  
Part No : MR 80B 6 230/400 50  
Part No : MR 80B 6 230/400 50  
Part No : MR 80B 6 230/400 50  
Part No : MR 80B 6 230/400 50  
Part No : MR 80B 6 230/400 50  
Part No : MR 90S2 B14  
Part No : MR 90S2 B14  
Part No : MR 90S2 B14  
Part No : MR 90S2 B14  
Part No : MR 90S2 B14  
Part No : MR 90S2 B14  
Part No : MR 90S2 B14  
Part No : MR 90S2 B14  
Part No : MR 90S2 B14  
Part No : MR100A4  
Part No : MR100B4  
Part No : MR100B4  
Part No : MR100B4  
Part No : MR100B4  
Part No : MR100B4  
Part No : MR100B4  
Part No : MR100B4

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : MR100B4  
Part No : MR100B4  
Part No : MR100B4  
Part No : MR11J0001 112A-4  
Part No : MR11J0001 112A-4  
Part No : MR11J0001 112A-4  
Part No : MR11J0001 112A-4  
Part No : MR11J0001 112A-4  
Part No : MR11J0001 112A-4  
Part No : MR11J0001 112A-4  
Part No : MR180M2-B5  
Part No : MR280M4  
Part No : MR28A0003  
Part No : MR63A0002  
Part No : MR63A0002  
Part No : MR63A0002  
Part No : MR63A0002  
Part No : MR63A0002  
Part No : MR63A0002  
Part No : MR63A0002  
Part No : MR63A0002  
Part No : MR63A0002  
Part No : MR63A0002  
Part No : MR63A0002  
Part No : MR63A0002  
Part No : MR63A0002  
Part No : MR63A0002  
Part No : MR63A0008  
Part No : MR63A0008  
Part No : MR63A0008  
Part No : MR63A0008  
Part No : MR63A0008  
Part No : MR63A0008  
Part No : MR63A0026 63B-4  
Part No : MR63A0026 63B-4  
Part No : MR63A0026 63B-4  
Part No : MR63A0026 63B-4  
Part No : MR63A0026 63B-4  
Part No : MR63A0026 63B-4

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : MR63A0026 63B-4  
Part No : MR63A0026 63B-4  
Part No : MR63A0026 63B-4  
Part No : MR63A2  
Part No : MR63C4-B14-0,25kW-1500  
Part No : MR63G0004 63B-4 N  
Part No : MR63G0004 63B-4 N  
Part No : MR63G0004 63B-4 N  
Part No : MR63G0004 63B-4 N  
Part No : MR63G0004 63B-4 N  
Part No : MR63G0004 63B-4 N  
Part No : MR63G0004 63B-4 N  
Part No : MR63G0004 63B-4 N  
Part No : MR63G0004 63B-4 N  
Part No : MR63G0004 63B-4 N  
Part No : MR63G0004 63B-4 N  
Part No : MR63T0004 63B-2 B5  
Part No : MR63T0004 63B-2 B5  
Part No : MR63T0004 63B-2 B5  
Part No : MR63T0004 63B-2 B5  
Part No : MR63T0004 63B-2 B5  
Part No : MR63T0004 63B-2 B5  
Part No : MR63T0004 63B-2 B5  
Part No : MR63T0004 63B-2 B5  
Part No : MR71A0001 71B-4 0.37KW 1375  
Part No : MR71A0001 71B-4 0.37KW 1375  
Part No : MR71A0001 71B-4 0.37KW 1375  
Part No : MR71A0001 71B-4 0.37KW 1375  
Part No : MR71A0001 71B-4 0.37KW 1375  
Part No : MR71A0001 71B-4 0.37KW 1375  
Part No : MR71A0001 71B-4 0.37KW 1375  
Part No : MR71A000171B-4  
Part No : MR71A000171B-4  
Part No : MR71A000171B-4  
Part No : MR71A000171B-4  
Part No : MR71A000171B-4

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : MR71A000171B-4

Part No : MR71A000171B-4

Part No : MR71A0005-71B-4

Part No : MR71A0042 71B-4

Part No : MR71A0042 71B-4

Part No : MR71A0042 71B-4

Part No : MR71A0042 71B-4

Part No : MR71A0042 71B-4

Part No : MR71A0042 71B-4

Part No : MR71A0042 71B-4

Part No : MR71A0042 71B-4

Part No : MR71A0042 71B-4

Part No : MR71A0050-71B-4

Part No : MR71A0050-71B-4

Part No : MR71A0050-71B-4

Part No : MR71A0050-71B-4

Part No : MR71A0050-71B-4

Part No : MR71A0050-71B-4

Part No : MR71A0050-71B-4

Part No : MR71A0050-71B-4

Part No : MR71A0061 71C4

Part No : MR71C4

Part No : MR80A-4 NR. 08031622

Part No : MR80A-4 NR. 08031622

Part No : MR80A-4 NR. 08031622

Part No : MR80A-4 NR. 08031622

Part No : MR80A-4 NR. 08031622

Part No : MR80A-4 NR. 08031622

Part No : MR80A0059 80B-4

Part No : MR80A00601 80A-4 â„–12329916037 (230/400) 0,5 kWt, 1370 rpm

Part No : MR80A00601 80A-4 â„–12329916037 (230/400) 0,5 kWt, 1370 rpm

Part No : MR80A00601 80A-4 â„–12329916037 (230/400) 0,5 kWt, 1370 rpm

Part No : MR80A00601 80A-4 â„–12329916037 (230/400) 0,5 kWt, 1370 rpm

Part No : MR80A00601 80A-4 â„–12329916037 (230/400) 0,5 kWt, 1370 rpm

Part No : MR80A00601 80A-4 â„–12329916037 (230/400) 0,5 kWt, 1370 rpm

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : MR80A00601 80A-4 â„–12329916037 (230/400) 0,5 kWt, 1370 rpm

Part No : MR80A0069 80B-4

Part No : MR80A0069 80B-4 â„–13072105279

Part No : MR80A0069 80B-4 â„–13072105279

Part No : MR80A0069 80B-4 â„–13072105279

Part No : MR80A0069 80B-4 â„–13072105279

Part No : MR80A0069 80B-4 â„–13072105279

Part No : MR80A0069 80B-4 â„–13072105279

Part No : MR80A0069 80B-4 â„–13072105279

Part No : MR80A0069 80B-4 â„–13072105279

Part No : MR80A0069 80B-4 â„–13072105279

Part No : MR80A0088 80A-4 0.66KW ,1644RPM

Part No : MR80A0088 80A-4 0.66KW ,1644RPM

Part No : MR80A0088 80A-4 0.66KW ,1644RPM

Part No : MR80A0088 80A-4 0.66KW ,1644RPM

Part No : MR80A0088 80A-4 0.66KW ,1644RPM

Part No : MR80A0088 80A-4 0.66KW ,1644RPM

Part No : MR80A0088 80A-4 0.66KW ,1644RPM

Part No : MR80A0088 80A-4 0.66KW ,1644RPM

Part No : MR80A0088 80A-4 0.66KW ,1644RPM

Part No : MR80A0088 80A-4 0.66KW ,1644RPM

Part No : MR80B-4

Part No : MR80B-4

Part No : MR80B-4

Part No : MR80B-4

Part No : MR80B-4

Part No : MR80B-4

Part No : MR80B-4

Part No : MR80B-4

Part No : MR80B4

Part No : MR80B4

Part No : MR80B4

Part No : MR80B4

Part No : MR80B4

Part No : MR80B4

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : MR80B4  
Part No : MR80B4  
Part No : MR80B4  
Part No : MR80B6  
Part No : MR80G0001 80A-4  
Part No : MR80G0013  
Part No : MR90-4  
Part No : MR90-4  
Part No : MR90-4  
Part No : MR90-4  
Part No : MR90-4  
Part No : MR90-4  
Part No : MR90-4  
Part No : MR90A0089  
Part No : MR90A0089-90L4  
Part No : MR90A0090 90L-4  
Part No : MR90A0106-90L6  
Part No : MR90A2026 90L-2  
Part No : MR90LB2  
Part No : MR90LB4  
Part No : MR90LBB4-B5  
Part No : MR90LBB4-B5  
Part No : MR90LBB4-B5  
Part No : MR90LBB4-B5  
Part No : MR90LBB4-B5  
Part No : MR90LBB4-B5  
Part No : MR90LBB4-B5  
Part No : MR90LBB4-B5  
Part No : MR90LBB4-B5  
Part No : MS 63B 2P OBSOLETE, REPLACEMENT DNB0R063B21-B14 / MR63B2!!!  
Part No : MS 63B 2P OBSOLETE, REPLACEMENT DNB0R063B21-B14 / MR63B2!!!  
Part No : MS 63B 2P OBSOLETE, REPLACEMENT DNB0R063B21-B14 / MR63B2!!!  
Part No : MS 63B 2P OBSOLETE, REPLACEMENT DNB0R063B21-B14 / MR63B2!!!  
Part No : MS 63B 2P OBSOLETE, REPLACEMENT DNB0R063B21-B14 / MR63B2!!!  
Part No : MS 63C 4P B14  
Part No : MS 71B 4P B5 OBSOLETE, REPLACEMT DNB0R071B41-B5 / MR71B4!!!

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : MS 71B 4P B5 OBSOLETE, REPLACEMT DNB0R071B41-B5 / MR71B4!!!  
Part No : MS 71B 4P B5 OBSOLETE, REPLACEMT DNB0R071B41-B5 / MR71B4!!!  
Part No : MS 71B 4P B5 OBSOLETE, REPLACEMT DNB0R071B41-B5 / MR71B4!!!  
Part No : MS 71B 4P B5 OBSOLETE, REPLACEMT DNB0R071B41-B5 / MR71B4!!!  
Part No : MS 71B 4P B5 OBSOLETE, REPLACEMT DNB0R071B41-B5 / MR71B4!!!  
Part No : MS 71B 4P B5 OBSOLETE, REPLACEMT DNB0R071B41-B5 / MR71B4!!!  
Part No : MST71B-4  
Part No : MST71B-4  
Part No : MST71B-4  
Part No : MST71B-4  
Part No : MST71B-4  
Part No : MST71B-4  
Part No : MST71B-4  
Part No : MST71B-4  
Part No : MST71B-4  
Part No : MST71B-4  
Part No : MST71B-4  
Part No : MST71B-4  
Part No : MST71B-4  
Part No : MST71B-4  
Part No : MST71B-4  
Part No : MST71B-4  
Part No : MST71B-4  
Part No : MST71B-4  
Part No : MST71B-4  
Part No : MST71B-4  
Part No : MST71B-4  
Part No : MST71B-4  
Part No : MST71B-4  
Part No : MST71B-4  
Part No : MST71B-4  
Part No : MST71B-4  
Part No : MST71B-4  
Part No : MST71B-4  
Part No : MVE71C4  
Part No : Mot 15x15  
Part No : Mot 15x15  
Part No : Mot 15x15  
Part No : Mot 15x15  
Part No : Mot 15x15  
Part No : Mot 15x15  
Part No : Mot 15x15  
Part No : Mot 15x15  
Part No : Mot 15x15  
Part No : Mot 15x15  
Part No : Mot 15x15  
Part No : Mot 15x15  
Part No : Mot 15x15  
Part No : Mot 15x15  
Part No : Mot 15x15  
Part No : Mot 15x15

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : N10.82/B5  
Part No : NERI MOTORI - 156A2  
Part No : NERI MOTORI - 17052361004003  
Part No : NERI MOTORI - 18050501001002  
Part No : NERI MOTORI - 20051545003003  
Part No : NERI MOTORI - 210P127530004  
Part No : NERI MOTORI - 21OP127530004  
Part No : NERI MOTORI - 220P152400006  
Part No : NERI MOTORI - AT100A  
Part No : NERI MOTORI - AT71C4  
Part No : NERI MOTORI - MR112A4  
Part No : NERI MOTORI - MR80G0013  
Part No : NERI MOTORI - T56A 009 2P B5 MULT+UL-CSA  
Part No : NERI MOTORI - T90L2  
Part No : NERI MOTORI - T90S8  
Part No : NMRV50 I=20 PAM 80 B5/0,68/70RPM  
Part No : NMRV50 I=20 PAM 80 B5/0,68/70RPM  
Part No : NMRV50 I=20 PAM 80 B5/0,68/70RPM  
Part No : NMRV50 I=20 PAM 80 B5/0,68/70RPM  
Part No : NMRV50 I=20 PAM 80 B5/0,68/70RPM  
Part No : NMRV50 I=20 PAM 80 B5/0,68/70RPM  
Part No : NMRV50 I=20 PAM 80 B5/0,68/70RPM  
Part No : NMRV50 I=20 PAM 80 B5/0,68/70RPM  
Part No : P-RTG 2.2KW  
Part No : RA80C2  
Part No : RM-320-4089  
Part No : RM-320-4089  
Part No : RM-320-4089  
Part No : RM-320-4089  
Part No : RM-320-4089  
Part No : RM-320-4089  
Part No : RM-320-4089  
Part No : RM-320-4089  
Part No : RM-320-4089  
Part No : RM-320-4089  
Part No : RM-320-4089

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)



Part No : S.T.M- RXO1 712 C1 C45 M1  
Part No : S1T90L4-IC411-10054153010  
Part No : S1T90L4-IC411-10054153010  
Part No : S1T90L4-IC411-10054153010  
Part No : S1T90L4-IC411-10054153010  
Part No : S1T90L4-IC411-10054153010  
Part No : S1T90L4-IC411-10054153010  
Part No : S1T90L4-IC411-10054153010  
Part No : S1T90L4-IC411-10054153010  
Part No : SERVOFAN 220 15 X 15  
Part No : SERVOFAN 220 15 X 15  
Part No : SERVOFAN 220 15 X 15  
Part No : SERVOFAN 220 15 X 15  
Part No : SERVOFAN 220 15 X 15  
Part No : SERVOFAN 220 15 X 15  
Part No : SERVOFAN 220 15 X 15  
Part No : SERVOFAN 220 15 X 15  
Part No : SERVOFAN 220 15 X 15  
Part No : SK109AP IC411 14012355001001  
Part No : SK109AP IC411 14012355001001  
Part No : SK109AP IC411 14012355001001  
Part No : SK109AP IC411 14012355001001  
Part No : SK109AP IC411 14012355001001  
Part No : SK109AP IC411 14012355001001  
Part No : SK127AP  
Part No : SK162AP  
Part No : SN/10054306001.  
Part No : SN20004559003002  
Part No : StatorgehÃuse fÃ¼r AI80B4, N. 15002555001001  
Part No : StatorgehÃuse fÃ¼r AI80B4, N. 15002555001001  
Part No : StatorgehÃuse fÃ¼r AI80B4, N. 15002555001001  
Part No : StatorgehÃuse fÃ¼r AI80B4, N. 15002555001001  
Part No : StatorgehÃuse fÃ¼r AI80B4, N. 15002555001001  
Part No : StatorgehÃuse fÃ¼r AI80B4, N. 15002555001001  
Part No : StatorgehÃuse fÃ¼r AI80B4, N. 15002555001001

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : Statorgehäuse für AI80B4, N. 15002555001001

Part No : Statorgehäuse für AI80B4, N. 15002555001001

Part No : T 080A 4

Part No : T 080A 4

Part No : T 080A 4

Part No : T 080A 4

Part No : T 080A 4

Part No : T 080A 4

Part No : T 080A 4

Part No : T 080A 4

Part No : T 080A 4

Part No : T 112B 2

Part No : T 112B 2

Part No : T 112B 2

Part No : T 112B 2

Part No : T 112B 2

Part No : T 112B 2

Part No : T 112B 2

Part No : T 112B 2

Part No : T 112B 2

Part No : T 112B 2

Part No : T 56B 4P B14

Part No : T 56B 4P B14

Part No : T 56B 4P B14

Part No : T 56B 4P B14

Part No : T 56B 4P B14

Part No : T 56B 4P B14

Part No : T 56B 4P B14

Part No : T 56B 4P B14

Part No : T 56B 4P B14

Part No : T 63 B 4

Part No : T 63 B 4

Part No : T 63 B 4

Part No : T 63 B 4

Part No : T 63 B 4

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : T 63 B 4  
Part No : T 63 B 4  
Part No : T 63 B 4  
Part No : T 63 B 4  
Part No : T 63 B 4  
Part No : T 63A 2  
Part No : T 63B 4  
Part No : T 63B 4  
Part No : T 63B 4  
Part No : T 63B 4  
Part No : T 63B 4  
Part No : T 63B 4  
Part No : T 63B 4  
Part No : T 63B 4  
Part No : T 63B 4  
Part No : T 63B 4  
Part No : T 63B 4  
Part No : T 63B 4 B14 230/400 50 C3 CL.H ATEX  
Part No : T 63B 4 B14 230/400 50 C3 CL.H ATEX  
Part No : T 63B 4 B14 230/400 50 C3 CL.H ATEX  
Part No : T 63B 4 B14 230/400 50 C3 CL.H ATEX  
Part No : T 63B 4 B14 230/400 50 C3 CL.H ATEX  
Part No : T 63B 4 B14 230/400 50 C3 CL.H ATEX  
Part No : T 63B 4 B14 230/400 50 C3 CL.H ATEX  
Part No : T 63B 4 EUROVOLTAGE  
Part No : T 63B 4 EUROVOLTAGE  
Part No : T 63B 4 EUROVOLTAGE  
Part No : T 63B 4 EUROVOLTAGE  
Part No : T 63B 4 EUROVOLTAGE  
Part No : T 63B 4 EUROVOLTAGE  
Part No : T 63B 4 EUROVOLTAGE  
Part No : T 63B 4 EUROVOLTAGE  
Part No : T 63B 4 EUROVOLTAGE  
Part No : T 63B 4 EUROVOLTAGE  
Part No : T 63B 4 EUROVOLTAGE  
Part No : T 63B4 B14 230/400 50 IP55 CLF  
Part No : T 63B4 B14 230/400 50 IP55 CLF

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : T 63B4 B14 230/400 50 IP55 CLF  
Part No : T 63B4 B14 230/400 50 IP55 CLF  
Part No : T 63B4 B14 230/400 50 IP55 CLF  
Part No : T 63B4 B14 230/400 50 IP55 CLF  
Part No : T 63B4 B14 230/400 50 IP55 CLF  
Part No : T 71A 4  
Part No : T 71A 4  
Part No : T 71A 4  
Part No : T 71A 4  
Part No : T 71A 4  
Part No : T 71A 4  
Part No : T 71A 4  
Part No : T 71A 4  
Part No : T 71A 4  
Part No : T 71A 4  
Part No : T 71B 4 KW 0.37 230/400 50 IP55 CLF  
Part No : T 71B 4 KW 0.37 230/400 50 IP55 CLF  
Part No : T 71B 4 KW 0.37 230/400 50 IP55 CLF  
Part No : T 71B 4 KW 0.37 230/400 50 IP55 CLF  
Part No : T 71B 4 KW 0.37 230/400 50 IP55 CLF  
Part No : T 71B 4 KW 0.37 230/400 50 IP55 CLF  
Part No : T 71B 4 KW 0.37 230/400 50 IP55 CLF  
Part No : T 71B 4 KW 0.37 230/400 50 IP55 CLF  
Part No : T 71B 4 KW 0.37 230/400 50 IP55 CLF  
Part No : T 71B 4 KW 0.37 230/400 50 IP55 CLF  
Part No : T 71B 4 KW 0.37 230/400 50 IP55 CLF  
Part No : T 71B 4 KW 0.37 230/400 50 IP55 CLF  
Part No : T 71C 2 230/400 50 TP111  
Part No : T 71C 2 230/400 50 TP111  
Part No : T 71C 2 230/400 50 TP111  
Part No : T 71C 2 230/400 50 TP111  
Part No : T 71C 2 230/400 50 TP111  
Part No : T 71C 2 230/400 50 TP111  
Part No : T 71C 2 230/400 50 TP111  
Part No : T 71C 2 230/400 50 TP111  
Part No : T 80B 4

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : T 80B 4  
Part No : T 80B 4  
Part No : T 80B 4  
Part No : T 80B 4  
Part No : T 80B 4  
Part No : T 80B 4  
Part No : T 90L 4 KW 1.50  
Part No : T 90L 4 KW 1.50  
Part No : T 90L 4 KW 1.50  
Part No : T 90L 4 KW 1.50  
Part No : T 90L 4 KW 1.50  
Part No : T 90L 4 KW 1.50  
Part No : T 90L 4 KW 1.50  
Part No : T 90L 4 KW 1.50  
Part No : T050B4  
Part No : T071B4B14  
Part No : T071B4B14  
Part No : T071B4B14  
Part No : T071B4B14  
Part No : T071B4B14  
Part No : T071B4B14  
Part No : T071B4B14  
Part No : T071B4B14  
Part No : T071B4B14  
Part No : T080B 4P B5  
Part No : T080B 4P B5  
Part No : T080B 4P B5  
Part No : T080B 4P B5  
Part No : T080B 4P B5  
Part No : T080B 4P B5  
Part No : T080B 4P B5  
Part No : T080B 4P B5  
Part No : T080B 4P B5  
Part No : T080B 4P B5  
Part No : T100 A4  
Part No : T100 A4  
Part No : T100 A4

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : T100 A4  
Part No : T100 A4  
Part No : T100 A4  
Part No : T100 A4  
Part No : T100 A4  
Part No : T100-B4  
Part No : T100A4  
Part No : T100B2  
Part No : T100BL4KW  
Part No : T100BL4KW  
Part No : T100BL4KW  
Part No : T100BL4KW  
Part No : T100BL4KW  
Part No : T100BL4KW  
Part No : T100BL4KW  
Part No : T112A6  
Part No : T112B2  
Part No : T112BL  
Part No : T112BL  
Part No : T112BL  
Part No : T112BL  
Part No : T112BL  
Part No : T112BL  
Part No : T112BL  
Part No : T112BL  
Part No : T112BL  
Part No : T112BL  
Part No : T112BL4  
Part No : T132M4  
Part No : T132M6  
Part No : T132ML  
Part No : T132ML  
Part No : T132ML  
Part No : T132ML  
Part No : T132ML  
Part No : T132ML  
Part No : T132ML  
Part No : T132ML

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : T132ML  
Part No : T132S4-B5  
Part No : T132SL2  
Part No : T160L.2  
Part No : T160L.2  
Part No : T160L.2  
Part No : T160L.2  
Part No : T160L.2  
Part No : T160L.2  
Part No : T160L.2  
Part No : T160L.2  
Part No : T160L.2  
Part No : T160L.2  
Part No : T160MA2  
Part No : T160MA2-B3-11kW-1500  
Part No : T50B2  
Part No : T50B4-B14-0,06kW-1500  
Part No : T50B4-B14-0,06kW-1500  
Part No : T50B4-B14-0,06kW-1500  
Part No : T50B4-B14-0,06kW-1500  
Part No : T50B4-B14-0,06kW-1500  
Part No : T50B4-B14-0,06kW-1500  
Part No : T50B4-B14-0,06kW-1500  
Part No : T50B4-B14-0,06kW-1500  
Part No : T50B4-B14-0,06kW-1500  
Part No : T56A  
Part No : T56A  
Part No : T56A  
Part No : T56A  
Part No : T56A  
Part No : T56A  
Part No : T56A  
Part No : T56A  
Part No : T56A  
Part No : T56A  
Part No : T56A  
Part No : T56A  
Part No : T56A  
Part No : T56A  
Part No : T56A  
Part No : T56A2 ATEX 400 50

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : T56A2 ATEX 400 50  
Part No : T56A2 ATEX 400 50  
Part No : T56A2 ATEX 400 50  
Part No : T56A2 ATEX 400 50  
Part No : T56A2 ATEX 400 50  
Part No : T56A2 ATEX 400 50  
Part No : T56A2 ATEX 400 50  
Part No : T56A4  
Part No : T56A4  
Part No : T56A4  
Part No : T56A4  
Part No : T56A4  
Part No : T56A4  
Part No : T56A4  
Part No : T56A4  
Part No : T56A4  
Part No : T56A4  
Part No : T56B4  
Part No : T56B4 B14  
Part No : T56B4 B14  
Part No : T56B4 B14  
Part No : T56B4 B14  
Part No : T56B4 B14  
Part No : T56B4 B14  
Part No : T56B4 B14  
Part No : T56B4 B14  
Part No : T56B4 B14  
Part No : T56B4 B14  
Part No : T56B4 IC411 12051429004 IP55  
Part No : T56B4, 09053208077  
Part No : T56B4, 09053208077  
Part No : T56B4, 09053208077  
Part No : T56B4, 09053208077  
Part No : T56B4, 09053208077  
Part No : T56B4, 09053208077

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net



Part No : T56B4, 09053208077  
Part No : T56B4, 09053208077  
Part No : T56B4, 09053208077  
Part No : T56B4, 230/400  
Part No : T56B4, 230/400  
Part No : T56B4, 230/400  
Part No : T56B4, 230/400  
Part No : T56B4, 230/400  
Part No : T56B4, 230/400  
Part No : T56B4, 230/400  
Part No : T56B4, 230/400  
Part No : T56B4, 230/400  
Part No : T56B4, 230/400  
Part No : T56B4, 230/400  
Part No : T56B4/IC411/13053985002001  
Part No : T56C/4  
Part No : T56C/4  
Part No : T56C/4  
Part No : T56C/4  
Part No : T56C/4  
Part No : T56C/4  
Part No : T56C/4  
Part No : T56C/4  
Part No : T56CN/4 Nr96100138  
Part No : T5OB4  
Part No : T63 B4 0,18 KW-4P  
Part No : T63 B4 0,18 KW-4P  
Part No : T63 B4 0,18 KW-4P  
Part No : T63 B4 0,18 KW-4P  
Part No : T63 B4 0,18 KW-4P  
Part No : T63 B4 0,18 KW-4P  
Part No : T63 B4 0,18 KW-4P  
Part No : T63 B4 0,18 KW-4P  
Part No : T63 B4 0,18 KW-4P  
Part No : T63 B4 0,18 KW-4P  
Part No : T63 B4-IP55 MOTOR+FAN 220 VAC  
Part No : T63 B4-IP55 MOTOR+FAN 220 VAC

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : T63 B4-IP55 MOTOR+FAN 220 VAC  
Part No : T63 B4-IP55 MOTOR+FAN 220 VAC  
Part No : T63 B4-IP55 MOTOR+FAN 220 VAC  
Part No : T63 B4-IP55 MOTOR+FAN 220 VAC  
Part No : T63 B4-IP55 MOTOR+FAN 220 VAC  
Part No : T63 B4-IP55 MOTOR+FAN 220 VAC  
Part No : T63-B4-XXX  
Part No : T63-B4-XXX  
Part No : T63-B4-XXX  
Part No : T63-B4-XXX  
Part No : T63-B4-XXX  
Part No : T63-B4-XXX  
Part No : T63-B4-XXX  
Part No : T63-B4-XXX  
Part No : T63-B4-XXX  
Part No : T6302  
Part No : T63A 013 4P B14  
Part No : T63A 013 4P B14  
Part No : T63A 013 4P B14  
Part No : T63A 013 4P B14  
Part No : T63A 013 4P B14  
Part No : T63A 013 4P B14  
Part No : T63A 013 4P B14  
Part No : T63A 013 4P B14  
Part No : T63A4  
Part No : T63A4B3  
Part No : T63B 4 208/360 60  
Part No : T63B 4 208/360 60  
Part No : T63B 4 208/360 60  
Part No : T63B 4 208/360 60  
Part No : T63B 4 208/360 60  
Part No : T63B 4 208/360 60  
Part No : T63B 4 208/360 60  
Part No : T63B 4 208/360 60  
Part No : T63B 4 208/360 60  
Part No : T63B1/05052726007  
Part No : T63B1/05052726007  
Part No : T63B1/05052726007

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : T63B1/05052726007  
Part No : T63B1/05052726007  
Part No : T63B1/05052726007  
Part No : T63B2  
Part No : T63B2 IC41 1 13002919001 TRIFASE IP65  
Part No : T63B4  
Part No : T63B4-B5  
Part No : T63B4.  
Part No : T63B4.  
Part No : T63B4.  
Part No : T63B4.  
Part No : T63B4.  
Part No : T63B4.  
Part No : T63B4.  
Part No : T63B4.  
Part No : T63B4.  
Part No : T63B4.  
Part No : T63B4.  
Part No : T63B4.  
Part No : T63B4.  
Part No : T63B6  
Part No : T63BN/6 OBSOLETE, REPLACEMENT DNB01063C61-B14 / IN63C6!!!  
Part No : T63BN/6 OBSOLETE, REPLACEMENT DNB01063C61-B14 / IN63C6!!!  
Part No : T63BN/6 OBSOLETE, REPLACEMENT DNB01063C61-B14 / IN63C6!!!  
Part No : T63BN/6 OBSOLETE, REPLACEMENT DNB01063C61-B14 / IN63C6!!!  
Part No : T63BN/6 OBSOLETE, REPLACEMENT DNB01063C61-B14 / IN63C6!!!  
Part No : T63BN/6 OBSOLETE, REPLACEMENT DNB01063C61-B14 / IN63C6!!!  
Part No : T63BN/6 OBSOLETE, REPLACEMENT DNB01063C61-B14 / IN63C6!!!  
Part No : T63BN/6 OBSOLETE, REPLACEMENT DNB01063C61-B14 / IN63C6!!!  
Part No : T63BN/6 OBSOLETE, REPLACEMENT DNB01063C61-B14 / IN63C6!!!  
Part No : T63C2 + ATEX 3D +CUSC.C3+ V3-TP111+ IP65  
Part No : T63C2 + ATEX 3D +CUSC.C3+ V3-TP111+ IP65  
Part No : T63C2 + ATEX 3D +CUSC.C3+ V3-TP111+ IP65  
Part No : T63C2 + ATEX 3D +CUSC.C3+ V3-TP111+ IP65  
Part No : T63C2 + ATEX 3D +CUSC.C3+ V3-TP111+ IP65  
Part No : T63C2 + ATEX 3D +CUSC.C3+ V3-TP111+ IP65  
Part No : T63C2 + ATEX 3D +CUSC.C3+ V3-TP111+ IP65  
Part No : T63C2 + ATEX 3D +CUSC.C3+ V3-TP111+ IP65  
Part No : T63C4

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : T63C4  
Part No : T63C4  
Part No : T63C4  
Part No : T63C4  
Part No : T63C4  
Part No : T63C4  
Part No : T63C4  
Part No : T63C4  
Part No : T63C4 06051337001  
Part No : T63C4 24074141010 IP55  
Part No : T63C4 24074141010 IP55  
Part No : T63C4 24074141010 IP55  
Part No : T63C4 24074141010 IP55  
Part No : T63C4 24074141010 IP55  
Part No : T63C4 24074141010 IP55  
Part No : T63C4 24074141010 IP55  
Part No : T63C4 24074141010 IP55  
Part No : T63C4 24074141010 IP55  
Part No : T63C6  
Part No : T63C6  
Part No : T63C6  
Part No : T63C6  
Part No : T63C6  
Part No : T63C6  
Part No : T63C6  
Part No : T63C6 replaced by DNB0I063C61-B5  
Part No : T63C6 replaced by DNB0I063C61-B5  
Part No : T63C6 replaced by DNB0I063C61-B5  
Part No : T63C6 replaced by DNB0I063C61-B5  
Part No : T63C6 replaced by DNB0I063C61-B5  
Part No : T63C6 replaced by DNB0I063C61-B5  
Part No : T63C6 replaced by DNB0I063C61-B5  
Part No : T63C6 replaced by DNB0I063C61-B5  
Part No : T63C8  
Part No : T63D4

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : T63D4-B14-0

Part No : T63D4.

Part No : T71 B2 PB5 MOTOR 0,55KW+FAN 220VAC

Part No : T71 B2 PB5 MOTOR 0,55KW+FAN 220VAC

Part No : T71 B2 PB5 MOTOR 0,55KW+FAN 220VAC

Part No : T71 B2 PB5 MOTOR 0,55KW+FAN 220VAC

Part No : T71 B2 PB5 MOTOR 0,55KW+FAN 220VAC

Part No : T71 B2 PB5 MOTOR 0,55KW+FAN 220VAC

Part No : T71 B2 PB5 MOTOR 0,55KW+FAN 220VAC

Part No : T71 B2 PB5 MOTOR 0,55KW+FAN 220VAC

Part No : T71 B2 PB5 MOTOR 0,55KW+FAN 220VAC

Part No : T71A2

Part No : T71A2

Part No : T71A2

Part No : T71A2

Part No : T71A2

Part No : T71A2

Part No : T71A2

Part No : T71A2

Part No : T71A2

Part No : T71A4

Part No : T71A4 11050715019

Part No : T71A4 1750RPM

Part No : T71A4-B5

Part No : T71B 037 4P B5

Part No : T71B 037 4P B5

Part No : T71B 037 4P B5

Part No : T71B 037 4P B5

Part No : T71B 037 4P B5

Part No : T71B 037 4P B5

Part No : T71B 037 4P B5

Part No : T71B 037 4P B5

Part No : T71B/4

Part No : T71B/4

Part No : T71B/4

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : T71B/4  
Part No : T71B/4  
Part No : T71B4  
Part No : T71B4  
Part No : T71B4  
Part No : T71B4  
Part No : T71B4  
Part No : T71B4  
Part No : T71B4  
Part No : T71B4  
Part No : T71B4  
Part No : T71B4 0.37 KW 1500 RPM  
Part No : T71B4 0.37 KW 1500 RPM  
Part No : T71B4 0.37 KW 1500 RPM  
Part No : T71B4 0.37 KW 1500 RPM  
Part No : T71B4 0.37 KW 1500 RPM  
Part No : T71B4 0.37 KW 1500 RPM  
Part No : T71B4 B5  
Part No : T71B4 B5  
Part No : T71B4 B5  
Part No : T71B4 B5  
Part No : T71B4 B5  
Part No : T71B4 B5  
Part No : T71B4 B5  
Part No : T71B4 B5  
Part No : T71B4 IC41  
Part No : T71B4 IC41  
Part No : T71B4 IC41  
Part No : T71B4 IC41  
Part No : T71B4 IC41  
Part No : T71B4 IC41  
Part No : T71B4 IC41  
Part No : T71B4 IC41  
Part No : T71B4 IC41  
Part No : T71B4-B5-0,37kW-1500  
Part No : T71B4-B?

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : T71B4-B?  
Part No : T71B4-B?  
Part No : T71B4-B?  
Part No : T71B4-B?  
Part No : T71B4-B?  
Part No : T71B4-B?  
Part No : T71B4-B?  
Part No : T71B4-B?  
Part No : T71B4-B?  
Part No : T71C6-B5  
Part No : T7W4  
Part No : T7W4  
Part No : T7W4  
Part No : T7W4  
Part No : T7W4  
Part No : T7W4  
Part No : T7W4  
Part No : T7W4  
Part No : T7W4  
Part No : T7W4  
Part No : T7W4  
Part No : T7W4  
Part No : T80 B2 1,1KW 2850  
Part No : T80 B2 1,1KW 2850 09053200008  
Part No : T80 B6  
Part No : T80A2 230/400 50  
Part No : T80A2 230/400 50 IP65  
Part No : T80A2 230/400 50 IP65  
Part No : T80A2 230/400 50 IP65  
Part No : T80A2 230/400 50 IP65  
Part No : T80A2 230/400 50 IP65  
Part No : T80A2 230/400 50 IP65  
Part No : T80A2 230/400 50 IP65  
Part No : T80A2 230/400 50 IP65  
Part No : T80A2 230/400 50 IP65  
Part No : T80A2 230/400 50 IP65  
Part No : T80A4  
Part No : T80A4 230/400 50

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : T80A8  
Part No : T80A8  
Part No : T80A8  
Part No : T80A8  
Part No : T80A8  
Part No : T80A8  
Part No : T80A8  
Part No : T80A8  
Part No : T80B4  
Part No : T80B4-B5  
Part No : T80B6 B5 220/380 60  
Part No : T80B6 B5 220/380 60  
Part No : T80B6 B5 220/380 60  
Part No : T80B6 B5 220/380 60  
Part No : T80B6 B5 220/380 60  
Part No : T80B6 B5 220/380 60  
Part No : T80B6 B5 220/380 60  
Part No : T80B6 B5 220/380 60  
Part No : T80B6 B5 220/380 60  
Part No : T80B6 B5 220/380 60  
Part No : T80BN/4  
Part No : T80BN/4  
Part No : T80BN/4  
Part No : T80BN/4  
Part No : T80BN/4  
Part No : T80BN/4  
Part No : T80BN/4  
Part No : T80BN/4  
Part No : T80C2  
Part No : T80D2  
Part No : T80D4 B14  
Part No : T80D4 IC 41 10050898004  
Part No : T80D4 IC 41 10050898004  
Part No : T80D4 IC 41 10050898004  
Part No : T80D4 IC 41 10050898004

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)



Part No : T80D4 IC 41 10050898004  
Part No : T80D4 IC 41 10050898004  
Part No : T80D4,16012459001001  
Part No : T80D4,16012459001001  
Part No : T80D4,16012459001001  
Part No : T80D4,16012459001001  
Part No : T80D4,16012459001001  
Part No : T80D4,16012459001001  
Part No : T80D4,16012459001001  
Part No : T80D4,16012459001001  
Part No : T80D4,16012459001001  
Part No : T90BL6-B5  
Part No : T90L  
Part No : T90L  
Part No : T90L  
Part No : T90L  
Part No : T90L  
Part No : T90L  
Part No : T90L  
Part No : T90L-4  
Part No : T90L-4 SN15010670001029  
Part No : T90L2-B34-UL-SON  
Part No : T90L4  
Part No : T90L4 08011792004  
Part No : T90L4 08011792004  
Part No : T90L4 08011792004  
Part No : T90L4 08011792004  
Part No : T90L4 08011792004  
Part No : T90L4 08011792004  
Part No : T90L4 08011792004  
Part No : T90LB 1,8 4P B14  
Part No : T90LB 1,8 4P B14  
Part No : T90LB 1,8 4P B14  
Part No : T90LB 1,8 4P B14  
Part No : T90LB 1,8 4P B14  
Part No : T90LB 1,8 4P B14

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : T90LB 1,8 4P B14

Part No : T90LB 1,8 4P B14

Part No : T90LB 1,8 4P B14

Part No : T90LB 1,8 4P B14

Part No : T90LB2

Part No : T90LB4

Part No : T90LB4-IC411-11011142001

Part No : T90S4 B14

Part No : T90S6 / 2106119100

Part No : T90S6 / 2106119100

Part No : T90S6 / 2106119100

Part No : T90S6 / 2106119100

Part No : T90S6 / 2106119100

Part No : T90S6 / 2106119100

Part No : T90S6 / 2106119100

Part No : T90S6 / 2106119100

Part No : T90S6 / 2106119100

Part No : T90S6 / 2106119100

Part No : T90S6 / 2106119100

Part No : T90S6 / 2106119100

Part No : T90S8

Part No : T9OS

Part No : T9OS

Part No : T9OS

Part No : T9OS

Part No : T9OS

Part No : T9OS

Part No : T9OS

Part No : T9OS

Part No : T9OS

Part No : T9OS

Part No : T9OS

Part No : TERMINAL BOX COVER for MS802-4 B14

Part No : TERMINAL BOX COVER for MS802-4 B14

Part No : TERMINAL BOX COVER for MS802-4 B14

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States  
Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web:  
<http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : TERMINAL BOX COVER for MS802-4 B14

Part No : TERMINAL BOX COVER for MS802-4 B14

Part No : TERMINAL BOX COVER for MS802-4 B14

Part No : TERMINAL BOX COVER for MS802-4 B14

Part No : TX80B4

Part No : TX80B4

Part No : TX80B4

Part No : TX80B4

Part No : TX80B4

Part No : TX80B4

Part No : TX80B4

Part No : TYP: MR80A0060 89A-4 NR.: 12329916089

Part No : TYP: MR80A0060 89A-4 NR.: 12329916089

Part No : TYP: MR80A0060 89A-4 NR.: 12329916089

Part No : TYP: MR80A0060 89A-4 NR.: 12329916089

Part No : TYP: MR80A0060 89A-4 NR.: 12329916089

Part No : TYP: MR80A0060 89A-4 NR.: 12329916089

Part No : TYPE: 1 MC71C4 SER NO: 06003964149 0.37 KW

Part No : TYPE: 1 MC71C4 SER NO: 06003964149 0.37 KW

Part No : TYPE: 1 MC71C4 SER NO: 06003964149 0.37 KW

Part No : TYPE: 1 MC71C4 SER NO: 06003964149 0.37 KW

Part No : TYPE: 1 MC71C4 SER NO: 06003964149 0.37 KW

Part No : TYPE: 1 MC71C4 SER NO: 06003964149 0.37 KW

Part No : TYPE: 1 MC71C4 SER NO: 06003964149 0.37 KW

Part No : TYPE: 1 MC71C4 SER NO: 06003964149 0.37 KW

Part No : TYPE: 1 MC71C4 SER NO: 06003964149 0.37 KW

Part No : TYPE: MR80G0011 80B-4

Part No : TYPE: MR80G0011 80B-4

Part No : TYPE: MR80G0011 80B-4

Part No : TYPE: MR80G0011 80B-4

Part No : TYPE: MR80G0011 80B-4

Part No : TYPE: MR80G0011 80B-4

Part No : TYPE: MR80G0011 80B-4

Part No : TYPE: MR80G0011 80B-4

Part No : TYPE: MR80G0011 80B-4

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : TYPE: T112A4 N: 08000821003

Part No : TYPE: T112A4 N: 08000821003

Part No : TYPE: T112A4 N: 08000821003

Part No : TYPE: T112A4 N: 08000821003

Part No : TYPE: T112A4 N: 08000821003

Part No : TYPE: T112A4 N: 08000821003

Part No : Three Phase Motor MAF80A4

Part No : Three Phase Motor MAF80A4

Part No : Three Phase Motor MAF80A4

Part No : Three Phase Motor MAF80A4

Part No : Three Phase Motor MAF80A4

Part No : Three Phase Motor MAF80A4

Part No : Three Phase Motor MAF80A4

Part No : Three Phase Motor MAF80A4

Part No : Three Phase Motor MAF80A4

Part No : Typ MSB802-4, Nr.13011161589 Obsolete, replacement by AT 80B 4 KW  
0.75 4P B14 230/400 50

Part No : Typ MSB802-4, Nr.13011161589 Obsolete, replacement by AT 80B 4 KW  
0.75 4P B14 230/400 50

Part No : Typ MSB802-4, Nr.13011161589 Obsolete, replacement by AT 80B 4 KW  
0.75 4P B14 230/400 50

Part No : Typ MSB802-4, Nr.13011161589 Obsolete, replacement by AT 80B 4 KW  
0.75 4P B14 230/400 50

Part No : Typ MSB802-4, Nr.13011161589 Obsolete, replacement by AT 80B 4 KW  
0.75 4P B14 230/400 50

Part No : Typ MSB802-4, Nr.13011161589 Obsolete, replacement by AT 80B 4 KW  
0.75 4P B14 230/400 50

Part No : Typ MSB802-4, Nr.13011161589 Obsolete, replacement by AT 80B 4 KW  
0.75 4P B14 230/400 50

Part No : Typ MSB802-4, Nr.13011161589 Obsolete, replacement by AT 80B 4 KW  
0.75 4P B14 230/400 50

Part No : Typ MSB802-4, Nr.13011161589 Obsolete, replacement by AT 80B 4 KW  
0.75 4P B14 230/400 50

Part No : Typ MSB802-4, Nr.13011161589 Obsolete, replacement by AT 80B 4 KW  
0.75 4P B14 230/400 50

Part No : Typ MSB802-4, Nr.13011161589 Obsolete, replacement by AT 80B 4 KW  
0.75 4P B14 230/400 50

Part No : Type: 13052170002

Part No : Type: 13052170002

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States  
Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web:  
<http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : Type: 13052170002  
Part No : Type: 13052170002  
Part No : Type: 13052170002  
Part No : Type: 13052170002  
Part No : Type: 13052170002  
Part No : Type: 13052170002  
Part No : Type: MK 90J0073 90LB-2  
Part No : Type: MK 90J0073 90LB-2  
Part No : Type: MK 90J0073 90LB-2  
Part No : Type: MK 90J0073 90LB-2  
Part No : Type: MK 90J0073 90LB-2  
Part No : Type: MK 90J0073 90LB-2  
Part No : Type: MK 90J0073 90LB-2  
Part No : Type: MK 90J0073 90LB-2  
Part No : VF 44 F1 70 P63 B5 B3  
Part No : VF 44 F1 70 P63 B5 B3  
Part No : VF 44 F1 70 P63 B5 B3  
Part No : VF 44 F1 70 P63 B5 B3  
Part No : VF 44 F1 70 P63 B5 B3  
Part No : VF 44 F1 70 P63 B5 B3  
Part No : VF 44 F1 70 P63 B5 B3  
Part No : VF 44 F1 70 P63 B5 B3  
Part No : brake adapter for motor AT63B6  
Part No : brake adapter for motor AT63B6  
Part No : brake adapter for motor AT63B6  
Part No : brake adapter for motor AT63B6  
Part No : brake adapter for motor AT63B6  
Part No : brake adapter for motor AT63B6  
Part No : brake adapter for motor AT63B6  
Part No : brake adapter for motor AT63B6  
Part No : brake adapter for motor AT63B6  
Part No : brake adapter for motor AT63B6  
Part No : brake adapter for motor AT63B6  
Part No : complete brake for AI80B4  
Part No : complete brake for AI80B4

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : complete brake for AI80B4  
Part No : complete brake for AI80B4  
Part No : complete brake for AI80B4  
Part No : complete brake for AI80B4  
Part No : complete brake for AI80B4  
Part No : complete brake for AI80B4  
Part No : complete brake for AI80B4  
Part No : coupler for motor M1 MC 74C4  
Part No : coupler for motor M1 MC 74C4  
Part No : coupler for motor M1 MC 74C4  
Part No : coupler for motor M1 MC 74C4  
Part No : coupler for motor M1 MC 74C4  
Part No : coupler for motor M1 MC 74C4  
Part No : coupler for motor M1 MC 74C4  
Part No : coupler for motor M1 MC 74C4  
Part No : coupler for motor M1 MC 74C4  
Part No : repair kit for M3-T112A2/SN:13008806002002  
Part No : repair kit for M3-T112A2/SN:13008806002002  
Part No : repair kit for M3-T112A2/SN:13008806002002  
Part No : repair kit for M3-T112A2/SN:13008806002002  
Part No : repair kit for M3-T112A2/SN:13008806002002  
Part No : repair kit for M3-T112A2/SN:13008806002002  
Part No : repair kit for M3-T112A2/SN:13008806002002  
Part No : repair kit for M3-T112A2/SN:13008806002002  
Part No : repair kit for M3-T112A2/SN:13008806002002